



PALM STREET WATER PLANT CONDITION ASSESSMENT

Prepared for:

City of Huntsville

July 31, 2015



Prepared by:

FREESE AND NICHOLS, INC.
11200 Broadway Street
Offices West, Suite 2332
Pearland, TX 77584
832-456-4700

DRAFT

PALM STREET WATER PLANT CONDITION ASSESSMENT

Prepared for:

City of Huntsville

DRAFT

THIS DOCUMENT IS RELEASED FOR
THE PURPOSE OF INTERIM REVIEW
UNDER THE AUTHORITY OF **WILLIAM
C. HERNDON, P.E.**, TEXAS NO. **97312**
ON **7/31/15**. IT IS NOT TO BE USED
FOR CONSTRUCTION, BIDDING OR
PERMIT PURPOSES.
FREESE AND NICHOLS, INC.
TEXAS REGISTERED ENGINEERING
FIRM F- 2144

Prepared by:

FREESE AND NICHOLS, INC.

11200 Broadway Street
Offices West, Suite 2332
Pearland, TX 77584
832-456-4700

HVL15274

TABLE OF CONTENTS

EXECUTIVE SUMMARY	1
1.0 INTRODUCTION.....	3
2.0 CONDITION ASSESSMENT METHODOLOGY	4
2.1 Condition Assessment Scoring.....	4
2.2 Criticality Assessment Scoring.....	4
2.3 Risk Determination	5
3.0 WATER PLANT ASSESSMENT	6
3.1 Old Pump Station.....	6
3.1.1 Overview	6
3.1.2 MCC.....	7
3.1.3 Alternate Power.....	8
3.1.4 HVAC	8
3.1.5 Piping.....	9
3.1.6 Valves.....	10
3.1.7 Pumps.....	11
3.1.8 Motors	12
3.1.9 Crane.....	12
3.1.10 Walls.....	13
3.1.11 Roof	14
3.1.12 Foundation	15
3.1.13 Instrumentation/Controls.....	15
3.1.14 SCADA.....	16
3.2 New Pump Station	17
3.2.1 Overview	17
3.2.2 MCC.....	18
3.2.3 Alternate Power.....	18
3.2.4 HVAC	19
3.2.5 Piping.....	22
3.2.6 Valves.....	22
3.2.7 Pumps.....	24
3.2.8 Motors	25
3.2.9 Crane.....	26
3.2.10 Walls.....	26
3.2.11 Roof	27

3.2.12	Foundation	28
3.2.13	Chlorine Analyzer	29
3.2.14	Instrumentation/Controls	30
3.2.15	SCADA	31
3.3	Other Site Items	32
3.3.1	Site Drainage	32
3.3.2	New Pump Station Discharge Meter	32
3.3.3	Entrance Gate	33
3.3.4	Video Surveillance	33
3.3.5	Tank Overflows	34
3.3.6	Fencing	35
3.3.7	Yard Piping	35
3.4	Risk Assessment Summary	35
4.0	FILTERS	37
5.0	RECOMMENDATIONS	40
5.1	Recommended Improvements & Cost Summary	40
5.2	Schedule	41
6.0	CONSTRUCTION OF A NEW PUMP STATION	44

Table of Figures

Figure 1:	Filters Isometric View	38
Figure 2:	Filters Plan	39
Figure 3:	New Pump Station Potential Site	44
Figure 4:	New Pump Station Plan	45
Figure 5:	New Pump Station Section	46

Table of Tables

Table 1:	Recommendations Summary	1
Table 2:	Condition Assessment Scoring Legend	4
Table 3:	Criticality Assessment Scoring Factors	4
Table 4:	Criticality Assessment Scoring Legend	5
Table 5:	Risk Determination Based on Condition and Criticality Ratings	5
Table 6:	MCC Rating	7
Table 7:	Alternate Power Rating	8
Table 8:	HVAC Rating	9
Table 9:	Piping Rating	10

Table 10:	Valves Rating.....	10
Table 11:	Pumps Rating	12
Table 12:	Motors Rating	12
Table 13:	Crane Rating.....	13
Table 14:	Walls Rating	14
Table 15:	Roof Rating.....	15
Table 16:	Foundation Rating.....	15
Table 17:	Instrumentation/Controls Rating.....	16
Table 18:	SCADA Rating	16
Table 19:	MCC Rating.....	18
Table 20:	Alternate Power Rating.....	19
Table 21:	HVAC Rating	21
Table 22:	Piping Rating	22
Table 23:	Valves Rating.....	23
Table 24:	Pumps Rating	25
Table 25:	Motors Rating	26
Table 26:	Crane Rating.....	26
Table 27:	Walls Rating	27
Table 28:	Roof Rating.....	28
Table 29:	Foundation Rating.....	29
Table 30:	Chlorine Analyzer Rating.....	30
Table 31:	Instrumentation/Controls Rating.....	31
Table 32:	SCADA Rating	31
Table 33:	Site Drainage Rating.....	32
Table 34:	New Pump Station Discharge Meter Rating	33
Table 35:	Entrance Gate Rating	33
Table 36:	Video Surveillance Rating	34
Table 37:	Tank Overflows Rating	34
Table 38:	Fencing Rating.....	35
Table 39:	Yard Piping Rating	35
Table 40:	Risk Assessment Summary.....	35
Table 41:	Recommended Improvements Summary	40
Table 42:	Schedule Alternate 1.....	42
Table 43:	Schedule Alternate 2.....	42
Table 44:	Schedule Alternate 3.....	43

APPENDICES

Appendix A – Condition Assessment Scoring Sheets
Appendix B – Detailed Cost Breakdown
Appendix C – Smith Pump Co. Pump Assessment

EXECUTIVE SUMMARY

The City of Huntsville's Palm Street Water Plant consists of two pump stations, referred to as the old and new pump stations. The old pump station was built in 1960 and the new pump station was added in 1983. The old pump station has performed exceptionally well over time requiring only one motor replacement and no pump replacements. The new pump station has seen more problems with three of the four pumps being replaced since the original installation. Both pump stations have exceeded their expected service life and are in need of improvements to continue providing the City of Huntsville with a reliable source of water. To this end, the City has contracted with Freese and Nichols, Inc. (FNI) to conduct a condition assessment to determine which components of the plant, specifically the pump stations, need improvements in order to continue serving the City.

A risk based assessment was conducted after a site visit and discussions with the City, based on this assessment the following recommended improvements with their risk rating and opinion of probable total project costs have been developed.

Table 1: Recommendations Summary

Facility	Component	Condition Rating	Criticality Rating	Risk	Opinion of Probable Total Project Cost*
Old PS	MCC	Poor	Very High	High Risk	\$246,200
New PS	MCC	Poor	Very High	High Risk	\$420,800
Old PS	Pumps	Poor	High	High Risk	\$172,000
New PS	Roof	Poor	Moderate	Moderate Risk	\$45,900
New PS	Instrumentation	Poor	Moderate	Moderate Risk	\$99,500
Old PS	Roof	Poor	Moderate	Moderate Risk	\$18,500
Old PS	Motors	Fair	High	Moderate Risk	\$75,100
New PS	Pumps	Fair	High	Moderate Risk	\$57,500
New PS	Motors	Fair	High	Moderate Risk	\$55,600
Old PS	Alternate Power	Good	Very High	Moderate Risk	\$23,000
Old PS	HVAC	Poor	Low	Moderate Risk	\$22,100
Old PS	Valves	Poor	Low	Moderate Risk	\$50,400
New PS	HVAC	Poor	Moderate	Moderate Risk	\$32,600
New PS	Valves	Poor	Low	Moderate Risk	\$45,600
Other	New PS Discharge Meter	Poor	Low	Moderate Risk	\$65,700
Old PS	Walls	Fair	Moderate	Moderate Risk	\$13,900
Other	Yard Piping	Fair	Moderate	Moderate Risk	\$51,500
New PS	Alternate Power	Very Good	Very High	Moderate Risk	
Old PS	Piping	Fair	Low	Moderate Risk	\$44,400
New PS	Piping	Fair	Low	Moderate Risk	\$92,400

Facility	Component	Condition Rating	Criticality Rating	Risk	Opinion of Probable Total Project Cost*
Other	Tank Overflows	Fair	Low	Moderate Risk	\$80,000
New PS	Walls	Fair	Moderate	Moderate Risk	\$27,600
New PS	Foundation	Fair	Moderate	Moderate Risk	\$10,100
New PS	SCADA	Good	Moderate	Moderate Risk	\$61,200
Other	Site Drainage	Fair	Very Low	Low Risk	
Other	Entrance Gate	Fair	Very Low	Low Risk	
Other	Video Surveillance	Fair	Very Low	Low Risk	
Old PS	Crane	Good	Low	Low Risk	
New PS	Crane	Good	Low	Low Risk	
Old PS	Instrumentation	Good	Low	Low Risk	
New PS	Chlorine Analyzer	Good	Low	Low Risk	
Other	Fencing	Good	Low	Low Risk	
Old PS	SCADA	Very Good	Moderate	Low Risk	
Old PS	Foundation	Very Good	Moderate	Low Risk	
Miscellaneous Improvements				Low Risk	\$200,000
				Total:	\$2,011,600

* Cost includes mobilization, contingency, construction management, materials testing and professional services

Additionally, FNI evaluated the potential for adding filtration to the water plant. This is a feasible alternative to the City though the filters would need to be located across the street on the elevated storage tank site due to space constraints on the main Palm St. Water Plant site. Another alternative the City could consider is to locate smaller filtration units at each of the well sites that have the most water quality issues.

An alternative option available to the City is to construct a new pump station and abandon the two existing pump stations. Since the City is currently on one pressure plane, a dual pump station system is not necessary and potentially better system efficiencies could be realized by combining the pumping into one pump station. This would also provide the City an opportunity to simplify the piping network within the plant and have a pump station that will be completely new, as opposed to two rehabilitated pump stations. The same space that is currently available for the filtration site could also be used for the new pump station site. A high level estimate of the project cost for a 16.5 MGD firm capacity pump station is \$4.4 million.

1.0 INTRODUCTION

The City of Huntsville's Palm Street Water Plant consists of two pump stations, referred to as the old and new pump stations. The old pump station was built in 1960 and the new pump station was added in 1983. The old pump station has performed exceptionally well over time requiring only one motor replacement and no pump replacements. The new pump station has seen more problems with three of the four pumps being replaced since the original installation. Both pump stations have exceeded their expected service life and are in need of improvements to continue providing the City of Huntsville with a reliable source of water. To this end, the City has contracted with Freese and Nichols, Inc. (FNI) to conduct a condition assessment to determine which components of the plant, specifically the pump stations, need improvements in order to continue serving the City.

A site visit was conducted with the City and FNI on March 12, 2015 to collect data, take readings, and talk to the plant operator to help identify the needs. Smith Pump Co. visited the plant on June 1-3, 2015 to complete testing on the pumps in order to make the best recommendations about remaining pump life. Additionally, FNI met with the City on June 30, 2015 for a workshop to discuss initial findings and get input from the City on their priorities. Taking the data from these site visits and discussions FNI rated each component based on its condition and criticality to the system to determine the risk associated with that component. Each component was then prioritized by risk and ranked for the City to use in developing an improvements project to address the most critical needs to the plant.

FNI also evaluated the potential for implementing filters at the Palm Street Water Plant. It was determined that the footprint for the filter site was too large to fit on the Palm Street Water Plant site north of Palm St. but that there was available space on the site south of Palm St. A plan for the filter location has been included in this report.

During discussions with the City, it was suggested that a new pump station be evaluated to determine the feasibility and potential costs in comparison to a rehab project of the existing pump station. This evaluation will look at the pump station from a high level to give the City an idea of what it could cost, if the City decides to pursue this a more detailed evaluation would be necessary to understand the specifics of a new pump station.

2.0 CONDITION ASSESSMENT METHODOLOGY

In order to quantitatively assess the risk associated with each component at the water plant, a condition score and a criticality score have been assigned to rate each component. Using a risk-based approach allows the City to easily evaluate which components should be included in an improvements project and plan for a capital improvements project. Engineers use their judgement, expertise, and experience to assign the scores for condition and criticality of each component.

2.1 CONDITION ASSESSMENT SCORING

The condition is a measure of the probability of failure. There are many factors that are considered when assessing the condition, not limited to the physical condition, wear, damage, corrosion, vibration, noise, and functionality of the component. The table below describes the scale for determining the condition scores and what rating those scores reflect.

Table 2: Condition Assessment Scoring Legend

Condition Rating	Scoring Guidelines
1	Very good condition; no improvements recommended to maintain function
2	Good condition; minor improvements recommended to maintain function
3	Fair condition; improvements recommended to improve performance or efficiency
4	Poor condition; improvements recommended to maintain reliability
5	Very Poor condition; rehabilitation or replacement required

2.2 CRITICALITY ASSESSMENT SCORING

In addition to determining the probability of failure, it is important to evaluate the consequence of a failure. Performing a criticality assessment helps to determine the magnitude of the consequence of a failure. The factors that can impact the criticality of a component include pumping capacity, efficiency, environment, safety, and outage duration. Three quantifiable factors were used to determine the criticality score for each component. The following table shows these factors and the weight given to each factor.

Table 3: Criticality Assessment Scoring Factors

Criticality Factors and Weighting System					
Capacity Lost Due to Failure (50%)		Redundancy (20%)		Outage Duration (30%)	
1	No Loss	1	Full Redundancy	1	≤ 2 Days
3	Partial Loss	3	Partial Redundancy	3	3-14 Days
5	Complete Loss	5	No Redundancy	5	≥ 15 Days

Once each of these three factors are taken into account an overall score can be determined. The following table describes the scoring method to determine the impact of a failure of a component.

Table 4: Criticality Assessment Scoring Legend

Criticality Rating	Scoring Guidelines
1	Very Low Impact
2	Low Impact
3	Moderate Impact
4	High Impact
5	Very High Impact

2.3 RISK DETERMINATION

Once the condition and criticality of a component have been assessed it can be input into a risk matrix to determine the level of risk associated with the given component. Risk is a function of the condition and criticality ratings. Table 5 provides a guide for determining the risk with given condition and criticality ratings. These risk ratings are very helpful in determining which projects should be prioritized over others.

Table 5: Risk Determination Based on Condition and Criticality Ratings

		Condition					
		Very Good	Good	Fair	Poor	Very Poor	
Criticality	Very Low Impact	LOW RISK			MODERATE RISK		
	Low Impact						
	Moderate Impact	MODERATE RISK		HIGH RISK			
	High Impact						
	Very High Impact	MODERATE RISK		HIGH RISK			

3.0 WATER PLANT ASSESSMENT

3.1 OLD PUMP STATION

3.1.1 Overview

The Old Pump Station was built in 1960 and consists of four vertical turbine pumps. The two smaller pumps have a design capacity of 1,000 gpm while the two larger pumps can pump 2,000 gpm. There is a space allocated for a 5th pump in the pump station originally intended for future expansion. Only one motor has been replaced on the pumps since the original installation and the pumps have not been pulled for service in 14 years. The pumps are all original.

The pump station building is small and does not have an HVAC system. There is a 1.5 ton overhead crane for pulling pumps but due to the low ceiling it is difficult to pull pumps or motors and have space to move within the pump station. Additionally, there is no truck access at the entrance to the pump station.



3.1.2 MCC

The Motor Control Center (MCC) was installed in the 1960s, has passed its life expectancy of thirty years, and is no longer supported by the manufacturer. Individual MCC components will no longer be available after they fail. Parts are replaced with comparable components that will fit within the shallow buckets and safety clearances are compensated to get the equipment into working conditions. Wiring inside the MCC is insulated with cloth, which loses its protective properties over time and subjects the equipment to faults. Past faults are evident within the MCC by the indications of carbon deposits on the interior walls. Inside the MCC are water lines used to monitor the tank water level. Water pipe installed inside electrical gear is no longer a good practice because of the ramifications of water leaking on electrical wires, busses and components.



Table 6: MCC Rating

	Score	Rating
Condition	4	Poor Condition
Criticality	5	Very High Impact
Risk	9	High Risk

Recommendation: Replace wiring and the MCC.

3.1.3 Alternate Power

Utility and backup generator power comes through an automatic transfer switch. The generator and Automatic Transfer Switch (ATS) are new and were installed after Hurricane Rita. The automatic transfer switch is installed outdoors and is showing signs of corrosion due to condensation and possible water infiltration from conduits penetrating through the top of the enclosure. Condensation was present inside the ATS during the time of inspection. Conduits penetrating the top of the enclosure have been sealed to prevent further infiltration but the ATS cabinet is rarely opened and a new leak will not be immediately detected.

Table 7: Alternate Power Rating

	Score	Rating
Condition	2	Good Condition
Criticality	5	Very High Impact
Risk	7	Moderate Risk

Recommendation: Reroute conductors and conduits.

3.1.4 HVAC

The HVAC in the old pump station consists of a single thermostatically controlled gas-fired unit heater for freeze protection, a floor portable rolling fan to circulate air, and operable windows. The single unit heater is in good condition, but the lack of redundancy and the lack of a permanent ventilation system lead to the overall HVAC condition being considered poor. The pump station has operated without a permanent mechanical ventilation system since it was built, so the impact of the lack of a ventilation system is low.

It is recommended that a second unit heater be added to the space for redundancy, to ensure that if one unit heater fails, the other can protect the space from freezing. It is also recommended that a dedicated mechanical ventilation system be installed. Although the pump station has been operating without one, a dedicated mechanical ventilation system would help increase the motor life by preventing overheating. Installing this system would involve removing a section of windows on one side of the building, and replacing it with a motorized combination louver/damper for air intake. On the opposite wall, a wall-mounted propeller exhaust fan would be installed for cross ventilation. The fan would be controlled by a thermostat so that when the room reached a certain temperature setpoint, the fan would turn on, the damper would open, and the system would ventilate the space until the setpoint was reached.



Table 8: HVAC Rating

	Score	Rating
Condition	4	Poor Condition
Criticality	2	Low Impact
Risk	6	Moderate Risk

Recommendation: Install wall mounted exhaust fan, combination louver damper, and gas fired unit heater.

3.1.5 Piping

The piping at the Old Pump Station is original though it has been recoated since the original installation. The piping itself is in good condition but the coating has begun to crack and peel in some places. The pipe is made of ductile iron and will corrode if the coating is not repaired. The piping for the two larger pumps (Pumps 3 & 4) is not supported at the bends and valve the way the smaller pumps (Pumps 1 & 2) are supported.



Table 9: Piping Rating

	Score	Rating
Condition	3	Fair Condition
Criticality	2	Low Impact
Risk	5	Moderate Risk

Recommendation: Replace aboveground piping.

3.1.6 Valves

Pumps 1 & 2 have tilting disc check valves while Pumps 3 & 4 have double swing check valves. There are gate valves on the suction and discharge sides of the pumps. The condition of the suction side valves is not known but the discharge valves are inoperable. Plant operators indicated that the discharge valves have never been used. The coatings on these valves are also in need of reapplication. It is recommended that these valves be replaced to be able to isolate a pump to do maintenance or repairs.

Table 10: Valves Rating

	Score	Rating
Condition	4	Poor Condition
Criticality	2	Low Impact
Risk	6	Moderate Risk

Recommendation: Replace gate valves and check valves on the discharge pipe, implement valve operating routine to exercise isolation valves periodically.

3.1.7 Pumps

The pumps are Layne 12WMC and 12THC pumps originally installed in 1960. Each pump is in a different condition, but for the purposes of this report the overall condition has been given a 'poor' rating. Specifically, Pumps 1 & 2 are in poor condition, Pump 3 is in fair condition, and Pump 4 is in very poor condition. Below is a list of the notable issues with each pump.

- Pump 1
 - The discharge head is in good condition.
 - The coupling guard could not be removed.
 - The highest vibration reading is 0.918 in/sec rms, or seven (7) times higher than the HI limit.
- Pump 2
 - The discharge head is in good condition.
 - The coupling guard could not be removed.
 - The highest vibration reading is 0.297 in/sec rms, or two (2) times higher than the HI limit.
- Pump 3
 - The discharge head is in good condition.
 - The stuffing box is severely corroded and it appears the packing gland studs are gone.
 - The packing gland was not perpendicular to the shaft
 - The highest vibration reading is 0.189 in/sec rms, slightly higher than the HI limit.
- Pump 4
 - The discharge head is in good condition.
 - The stuffing box is severely corroded and it appears the packing gland studs are gone.
 - The packing gland was not perpendicular to the shaft
 - The highest vibration reading is 0.383 in/sec rms, or 2.5 times higher than the HI limit.

Generally these pumps are seeing vibration well above the recommended Hydraulic Institute (HI) limit. The vibration was tested by Smith Pump Co. and can be seen in Appendix C. The coupling guards are recommended to be replaced due to the difficulty in accessing the pump shaft. Visual inspection of the pump shaft indicated significant corrosion as well as a leaking seal. The hydraulic results from the pump tests were not realistic due to the non-ideal placement of the strap on flow meter. There was no straight section of pipe with adequate length available to obtain an accurate flow reading. Since these pumps are original and given the observed corrosion and vibration issues, it is likely that the pumps are not running very efficiently. Additionally, any cast parts are not likely to be available if a repair is needed.



Table 11: Pumps Rating

	Score	Rating
Condition	4	Poor Condition
Criticality	4	High Impact
Risk	8	High Risk

Recommendation: Replace all four pumps, due to age and unavailability of cast parts.

3.1.8 Motors

Motors on the three of the four pumps were manufactured in 1960 and have not been rewound or serviced, but are still running.

Table 12: Motors Rating

	Score	Rating
Condition	3	Fair Condition
Criticality	4	High Impact
Risk	7	Moderate Risk

Recommendation: Replace all four motors.

3.1.9 Crane

The 1-1/2 ton capacity manual trolley hoist and monorail beam is located over the pumps. The monorail beam is attached to the bottom of roof slab. Due to low roof slab height above floor, it is difficult to lift

pumps and/or motors and have space to move within the pump station room. The operation of the trolley hoist was not observed but visually the trolley hoist, chains, and hook appear to be in good condition. The monorail beam needs painting.

Table 13: Crane Rating

	Score	Rating
Condition	2	Good Condition
Criticality	2	Low Impact
Risk	4	Low Risk

Recommendation: No improvements recommended at this time.

3.1.10 Walls

The pump station is a structural concrete framed building with concrete slab roof, concrete beams, and concrete columns. The exterior walls are non-load bearing with glazed tile masonry on interior with exterior brick veneer. The interior face of concrete columns are clad with glazed tile.

The interior face of glazed tile is cracked at two columns on each side of one window. It appears the glazed tile may have become load bearing which resulted in cracking. Also, the glazed tile is cracked in one corner by an interior door. Exterior brick veneer is in good condition. Some minor rust spots were observed on steel lintel angles supporting brick veneer over windows and doors. The paint on exposed concrete beams is peeling and flaking.

No signs of distress in the concrete beams and columns was observed.

The office area was locked during site visit and was not accessed for observation.



Table 14: Walls Rating

	Score	Rating
Condition	3	Fair Condition
Criticality	3	Moderate Impact
Risk	6	Moderate Risk

Recommendation: Replace broken glazed tile and repaint.

3.1.11 Roof

The pump station roof is a concrete slab. No signs of distress in slab was observed from interior of pump station room. The paint on exposed bottom of concrete roof slab is peeling and flaking.

Two hairline cracks were observed on underside of exterior cantilevered roof slab at covered area adjacent to main entrance into pump station office area. There was evidence of water leaking through these hairline cracks.

A small area of the concrete roof slab at the edge of the overhang is cracking and starting to spall. This area is located above the pump station window on the side of the building with the LAS storage.

Gutter and roofing is damaged at edge of roof at front of pump station building. Access on roof was not provided, therefore, roofing was not observed.

Table 15: Roof Rating

	Score	Rating
Condition	4	Poor Condition
Criticality	3	Moderate Impact
Risk	7	Moderate Risk

Recommendation: Repair roofing, repair cracked/spalled concrete roof slab.

3.1.12 Foundation

From visual observations, the foundation/slab appears to be in very good condition. No signs of distress were observed. A few bearing bars on the floor grating are bent but do not present a structural problem.

Table 16: Foundation Rating

	Score	Rating
Condition	1	Very Good Condition
Criticality	3	Moderate Impact
Risk	4	Low Risk

Recommendation: No improvements recommended at this time.

3.1.13 Instrumentation/Controls

A pump controller is mounted to the front of an MCC door and is an older technology. The pump controller is used to automatically control the pumps based on level in the tanks. The manufacturer no longer supports the current controller and past repairs required the plant to send the controller to a third party repair service. The company supporting repairs has recently stopped repairing similar controllers for the lift stations. A manual control panel for the old and new pump station is located near the MCC and the pushbuttons, lights, and wiring needs to be updated for proper documentation. Over the years, repairs and modifications have not been documented and future repairs can become problematic to troubleshoot.




Table 17: Instrumentation/Controls Rating

	Score	Rating
Condition	2	Good Condition
Criticality	2	Low Impact
Risk	4	Low Risk

Recommendation: No improvements recommended at this time.

3.1.14 SCADA

SCADA hardware in the pump station has been recently replaced and is considered a low risk of failure. The chart recorders used to monitor pressures and flows are in working condition but are an older technology.

Table 18: SCADA Rating

	Score	Rating
Condition	1	Very Good Condition
Criticality	3	Moderate Impact
Risk	4	Low Risk

Recommendation: No improvements recommended at this time.

3.2 NEW PUMP STATION

3.2.1 Overview

The New Pump Station was built in 1983 consists of four horizontal split case pumps each with a design capacity of 1,750 gpm. Generally the City's operators have had more problems with this pump station than the old pump station. Three of the four pumps have been replaced since the original installation. There is a 2 ton overhead bridge crane for pulling pumps and equipment and good access for vehicles to enter through double sliding doors to the pump station.



3.2.2 MCC

The Motor Control Center (MCC), installed in the mid-1980s, has passed its life expectancy of thirty years and parts are not readily available. An infrared camera was used during the site visit and temperatures indicate the equipment is operating within manufacturers specifications. A few hot spots were detected at wire terminations which can be corrected by the City's electrician. Although the infrared camera is used to help determine the operating temperature of the equipment, failures can occur due to other protective characteristic changes due to age.



Table 19: MCC Rating

	Score	Rating
Condition	4	Poor Condition
Criticality	5	Very High Impact
Risk	9	High Risk

Recommendation: Replace wiring, MCC, and automatic transfer switch.

3.2.3 Alternate Power

Utility and backup generator power comes through an automatic transfer switch. The generator and Automatic Transfer Switch (ATS) were installed in 1984 and the generator has failed. A temporary generator has been installed. The automatic transfer switch currently works but is no longer supported by the manufacturer and replacement parts will not be available when current stock is sold out. A failure

of the ATS could leave the pump station out of service for an extended period of time. However, the City has recently begun a project to replace the generator. Therefore the condition rating is very good.



Table 20: Alternate Power Rating

	Score	Rating
Condition	1	Very Good Condition
Criticality	5	Very High Impact
Risk	6	Moderate Risk

Recommendation: No improvements recommended at this time due to the newly replaced generator.

3.2.4 HVAC

The HVAC assessment of the new pump station includes: the pump building, electrical building, chlorine room, and fluoride room. Together, the HVAC systems for these spaces have a moderate impact on the overall operation of the pump station. Each of the components is easy to replace if they were to fail, but in several cases the pump station may not be able to operate without these systems in place; such as if the exhaust fan in the electrical building went out, the electrical gear may overheat if operated.

The current HVAC system consists of a wall-mounted propeller exhaust fan, two wall-mounted gravity dampers, and a single electric unit heater. The ventilation system in the new pump station is operable, but in need of repair.



The exhaust fan is nearing the end of its useful life and should be replaced. Included in the fan replacement, should be a wall-collar, OSHA guards, and a weatherhood. The gravity dampers in the doors allow water penetration and should be replaced with combination louver/damper rated for wind-driven rain. The electric unit heater, used for freeze protection in the space, is nonfunctional and should be replaced. It is also recommended that a second unit heater be added for redundancy; this would insure that if one unit heater was to fail, the other would protect the pipes from freezing.

The ventilation system in the electrical building consists of a roof-mounted exhaust fan and a wall-mounted motorized louver/damper.

The exhaust fan appears to be nearing the end of its useful life, and replacement in the near future is recommended. Also, the motorized damper is no longer operable, the actuator no longer works and will not properly operate the damper. It is recommended it be replaced with a wall-mounted gravity backdraft combination louver/damper. This type of louver/damper does not require an actuator and would open when the exhaust fan is on, and close by gravity when the exhaust fan is off.

The HVAC system in the chlorine room consists of a wall-mounted exhaust fan and door louver, each mounted approximately 12" above finished floor. The chlorine room also has a portable electric unit heater, and a chlorine gas detection system with a single sensor. The overall ventilation system is in fair condition.

It is recommended that an air intake high in the wall should be added to allow ventilation air to sweep the entire room instead of the ventilation air coming in low from the current door louver. A thermostatically controlled wall-mounted unit heater should be added for freeze protection. The condition of the current

chlorine sensor is unknown, regular testing of the system should be implemented to ensure it remains operable. In addition, a second chlorine detector should be added for redundancy.

The ventilation system in the fluoride room consists of a wall-mounted exhaust fan, door mounted louver, and residential style grille installed in the wall above the door. The overall condition of the equipment is poor. The exhaust fan is highly corroded and almost no airflow is being allowed through. The grille above the door is not properly installed, is not the proper type, and allows water penetration

It is recommended the exhaust fan should be replaced immediately. Also, the grille high in the wall should be replaced with a properly installed industrial grade wall-mounted louver.




Table 21: HVAC Rating

	Score	Rating
Condition	4	Poor Condition
Criticality	3	Moderate Impact
Risk	7	Moderate Risk

Recommendation: Replace exhaust fan and louver damper in the new pump station. Install a chlorine detector, unit heater, and exhaust fan in the Chlorine room. Replace exhaust fan and louver in the Fluoride Room

3.2.5 Piping

The piping at the new pump station is steel and is in fair condition. There are a few segments where taps have been made or other work done on the pipe that have removed the coatings and have allowed for significant corrosion, specifically on Pump 1. There are also a few sections of pipe that have been damaged as evidenced through visible dents in the pipe. The suction piping does not follow HI standards due to the eccentric reducer being located too close to the pumps.




Table 22: Piping Rating

	Score	Rating
Condition	3	Fair Condition
Criticality	2	Low Impact
Risk	5	Moderate Risk

Recommendation: Replace piping and appurtenances.

3.2.6 Valves

Butterfly valves are currently utilized for both the suction and discharge sides of the pump. Some noise was observed by the upstream butterfly valve, which indicates turbulent flow and the potential for cavitation. Additionally, an older valve that had been pulled was still on site and showed evidence of significant corrosion. Flow characteristics through the pumps could be improved if the upstream butterfly valves were replaced with a full port valve.




Table 23: Valves Rating

	Score	Rating
Condition	4	Poor Condition
Criticality	2	Low Impact
Risk	6	Moderate Risk

Recommendation: Replace three 12" discharge side BFVs with motor operated actuator and replace suction side BFV's with 12" gate valves.

3.2.7 Pumps

The pumps are Goulds 3405 pumps and originally installed in 1983. Each pump is in a different condition, but for the purposes of this report the overall condition has been given a 'fair' rating. Specifically, Pumps 1 & 2 are in very good condition and Pumps 3 & 4 are in fair condition. Below is a list of the notable issues with each pump.

- Pump 1
 - The efficiency is low, likely caused by excessive wear ring clearance.
 - Very low vibration, maximum 0.076 in/sec rms.
 - The alignment is severely off and motor would be bolt bound
 - Suction piping configuration does not follow HI standards, an eccentric reducer is located too close to the suction of the pump.
- Pump 2
 - Very low vibration, maximum 0.052 in/sec rms.
 - The alignment is off
 - Suction piping configuration does not follow HI standards, an eccentric reducer is located too close to the suction of the pump.
- Pump 3
 - Very low vibration, maximum 0.028 in/sec rms.
 - The alignment is off
 - Suction piping configuration does not follow HI standards, an eccentric reducer is located too close to the suction of the pump.
- Pump 4
 - Vibration is close to HI limit, maximum was 0.139 in/sec rms.
 - The alignment is severely off but the motor feet are already directly on the motor pad and cannot be lowered any more
 - Suction piping configuration does not follow HI standards, an eccentric reducer is located too close to the suction of the pump.

Plant operators have indicated that these pumps have given them more difficulties than the pumps at the Old Pump Station. It was noted by Smith Pump Co. that several of the pump alignments were off. Most of the pumps had low vibration except for Pump 4 which was close to the HI limit but still below it. Pump curves were not available for pumps 2, 3, and 4, though the hydraulic performance appeared to be close to the pump curve for Pump 1.



Table 24: Pumps Rating

	Score	Rating
Condition	3	Fair Condition
Criticality	4	High Impact
Risk	7	Moderate Risk

Recommendation: Replace oldest pump and rehab the next two oldest pumps, the newest pump is not recommended for rehab at this time.

3.2.8 Motors

Pump motor disconnect copper blades are showing signs of surface corrosion. Surface corrosion on copper blades cause hot spots where copper on copper connections are made. Surface corrosion can cause a detrimental failure. The disconnect enclosures are rusting from the inside out.

Pump motors have periodically been replaced as they fail and the pump control valve actuators are no longer supported by the manufacturer. Replacement pump valve actuators are available from various manufacturers, but controls for the current valve actuators and pumps must be modified. Valve actuator manufacturers have made significant control modifications and do not require separate control panels. Modifications to the pump control system are required as the valve actuators get replaced.

Table 25: Motors Rating

	Score	Rating
Condition	3	Fair Condition
Criticality	4	High Impact
Risk	7	Moderate Risk

Recommendation: Replace the three oldest motors, the newest motor is not recommended for replacement at this time.

3.2.9 Crane

The bridge crane is a 2 ton capacity under running single girder bridge crane with trolley hoist. The operation of the bridge crane was not observed but visually the bridge crane, including trolley hoist, chains, hook, and runway beams, appear to be in good condition.

The fluoride and chlorine building has a 2 ton capacity manual trolley hoist. The operation of the trolley hoist was not observed but visually the trolley hoist, chains, and hook appear to be in fair condition. The chain and hook shows signs of light to moderate rusting.

Table 26: Crane Rating

	Score	Rating
Condition	2	Good Condition
Criticality	2	Low Impact
Risk	4	Low Risk

Recommendation: No improvements recommended at this time.

3.2.10 Walls

The pump station is a pre-engineered metal building on top of 2.5 feet high concrete perimeter wall and pedestals at columns. The structural steel framing, including columns and wall girts, are in fair to good condition. In three or four places, strap bracing is broken apart and is in very poor condition. There is water leakage at the top of wall and roof edge interface. The steel framing members in areas with leakage show signs of mild corrosion and the primer coating is peeling. The primer coating has been compromised at the steel jambs at the sliding doors. The exterior metal wall panels have several dents near the bottom probably due to being hit by lawn maintenance equipment or trailers. This damage to wall panels is only aesthetic and not structural. The insulation on the interior face of wall panels is in very poor condition with holes, tears, and sections falling apart.

The fluoride and chlorine building is a pre-engineered metal building with one-half of the building enclosed with masonry walls and metal wall panels. The other half of the building is open with canopy roof. The exterior exposed structural steel columns show signs of mild corrosion and the paint coating has failed at bottom of columns and base. Inside the chlorine room, there is mild rusting on the interior face of metal wall panels and steel framing. There are minor dents on exterior face of metal wall panels.

The electrical building is a pre-engineered metal building and is in good condition. There are minor dents on exterior face of metal wall panels.



Table 27: Walls Rating

	Score	Rating
Condition	3	Fair Condition
Criticality	3	Moderate Impact
Risk	6	Moderate Risk

Recommendation: Make repairs to fix leaks and repair/replace damage components and replace insulation.

3.2.11 Roof

The pump station roof is a standard pre-engineered metal building roof. The structural steel framing, including girders and purlins, are in good condition. In three or four places, strap bracing is broken apart and is in very poor condition. There is water leakage at the roof edge and top of wall interface. The steel framing members in areas with leakage show signs of mild corrosion and the primer coating is peeling.

Metal roof deck at corner adjacent to front door shows signs of moderate to severe corrosion. In this area, the roof deck's coating has failed, there is a small hole through deck, and was leaking while it was raining during the site visit. The insulation on the interior face of roof deck is in very poor condition with holes, tears, and sections falling apart.

The fluoride and chlorine building roof is a standard pre-engineered metal building roof. The structural steel framing, including girders and purlins, are in good condition, except inside the chlorine room, there is mild rusting on the steel framing members. There are minor dents on exterior face of metal wall panels.

The electrical building roof is a standard pre-engineered metal building roof and is in good condition.

Table 28: Roof Rating

	Score	Rating
Condition	4	Poor Condition
Criticality	3	Moderate Impact
Risk	7	Moderate Risk

Recommendation: Make repairs to fix leaks and repair/replace damage components and replace insulation.

3.2.12 Foundation

For the pump station, from visual observations, the concrete foundation/slab appears to be in fair to good condition. The concrete floor slab is isolated from the perimeter concrete grade beams/walls/pedestals and the concrete mat foundations supporting the pumps. The floor slab and the mat foundations supporting the pumps appear to be in fair to good condition. Some very minor settlement of the floor slab was observed. There is some minor concrete spalling at the expansion joints between the floor slab and the pumps' mat foundations. The joint sealant has failed. Grout under three or four pipe support bases was cracked and/or spalled.

For the fluoride and chlorine building, from visual observations, the concrete foundation/slab appears to be in good condition.

For the electrical building, from visual observations, the concrete foundation/slab appears to be in good condition.



Table 29: Foundation Rating

	Score	Rating
Condition	3	Fair Condition
Criticality	3	Moderate Impact
Risk	6	Moderate Risk

Recommendation: Repair concrete cracks/spalling, seal joints, and grout under pipe supports.

3.2.13 Chlorine Analyzer

While the existing analyzer is in good condition, the City prefers to have a new chlorine analyzer at the new pump station similar to the ProMinent Chlorine Analyzer that was recently installed at the old pump station.



Table 30: Chlorine Analyzer Rating

	Score	Rating
Condition	2	Good Condition
Criticality	2	Low Impact
Risk	4	Low Risk

Recommendation: No improvements recommended at this time, though an allowance for this item is included under miscellaneous improvements in the cost estimate.

3.2.14 Instrumentation/Controls

The pumps are controlled from either the old pump station or from a control station located in the new pump station. Control stations can wear out over time. Replacement parts are readily available. Modifications to the controls for pump number 1 have left little documentation for wiring causing potential extended outages due to troubleshooting.




Table 31: Instrumentation/Controls Rating

	Score	Rating
Condition	4	Poor Condition
Criticality	3	Moderate Impact
Risk	7	Moderate Risk

Recommendation: Replace pump controls and install new motor operated actuators

3.2.15 SCADA

The new pump station is connected to the old pump station SCADA system. The SCADA system is new and some modifications can be made to replace the outdated controller.

Table 32: SCADA Rating

	Score	Rating
Condition	2	Good Condition
Criticality	3	Moderate Impact
Risk	5	Moderate Risk

Recommendation: Replace outdated controller.

3.3 OTHER SITE ITEMS

3.3.1 Site Drainage

During the site visit it was observed that there was ponding in a few areas across the site, specifically, around the ground storage tanks and underneath the elevated storage tank. This is likely due to ground settlement after construction. While it does not appear to have caused any problems to date, it could allow for corrosion to begin at the base of the tanks.



Table 33: Site Drainage Rating

	Score	Rating
Condition	3	Fair Condition
Criticality	1	Very Low Impact
Risk	4	Low Risk

Recommendation: No improvements recommended at this time.

3.3.2 New Pump Station Discharge Meter

The flow meter on the discharge header of the New Pump Station is above ground in a vertical position directly downstream of a 135° bend. This does not meet the typical standard for mag meters which requires five upstream pipe diameters of straight pipe and 3 downstream pipe diameters of straight pipe. Relocating this valve to a straight section of pipe would provide more accurate readings for the flow coming from the New Pump Station.



Table 34: New Pump Station Discharge Meter Rating

	Score	Rating
Condition	4	Poor Condition
Criticality	2	Low Impact
Risk	6	Moderate Risk

Recommendation: Relocate new pump station discharge meter allowing for a longer straight run of pipe including a flow conditioner, all within a new vault.

3.3.3 Entrance Gate

Currently the Palm St. Water Plant has a double swing gate but plant operators noted that a roller gate would be preferred.

Table 35: Entrance Gate Rating

	Score	Rating
Condition	3	Fair Condition
Criticality	1	Very Low Impact
Risk	4	Low Risk

Recommendation: No improvements recommended at this time.

3.3.4 Video Surveillance

There is an existing camera at the entrance gate but this is the only video surveillance provided at the site. Plant operators noted that additional video surveillance would increase security at the plant.

Table 36: Video Surveillance Rating

	Score	Rating
Condition	3	Fair Condition
Criticality	1	Very Low Impact
Risk	4	Low Risk

Recommendation: No improvements recommended at this time.

3.3.5 Tank Overflows

The existing tank overflows discharge on the north side of the plant on a slope away from the tanks offsite towards an apartment complex. Under normal circumstances any overflow water would still drain away from the apartment complexes but there is some risk of erosion on the slope. High flows or unforeseen circumstances may put the adjacent apartment complex at risk of flooding. The tank overflow piping could be extended to the northeast to discharge into the drainage ditch to mitigate this risk.



Table 37: Tank Overflows Rating

	Score	Rating
Condition	3	Fair Condition
Criticality	2	Low Impact
Risk	5	Moderate Risk

Recommendation: Reroute overflow piping towards northeast corner of property away from the apartment complex

3.3.6 Fencing

Plant operators indicated that some fencing has been damaged in recent storms although it was minor and did not compromise the security of the facility.

Table 38: Fencing Rating

	Score	Rating
Condition	2	Good Condition
Criticality	2	Low Impact
Risk	4	Low Risk

Recommendation: No improvements recommended at this time.

3.3.7 Yard Piping

There is currently no isolation valve on the 3.0 MG ground storage tank on the east side of the site which prevents the City from being able to shut down that tank for maintenance without having to shut down other tanks. For operational flexibility it would be beneficial to add a valve there. Other piping around the site also appeared to be in need of some coating touch ups.

Table 39: Yard Piping Rating

	Score	Rating
Condition	3	Fair Condition
Criticality	3	Moderate Impact
Risk	6	Moderate Risk

Recommendation: Install 30" isolation valve on inlet to 3.0 MG ground storage tank.

3.4 RISK ASSESSMENT SUMMARY

Summarizing all of the component scores allows us to rank the components by risk. The components at the Palm St. Water Plant have been summarized to show this ranking and provide insight as to which components should be repaired or replaced before others.

Table 40: Risk Assessment Summary

Facility	Component	Condition	Condition Rating	Criticality	Criticality Rating	Risk
Old PS	MCC	4	Poor	5	Very High	High Risk
New PS	MCC	4	Poor	5	Very High	High Risk
Old PS	Pumps	4	Poor	4	High	High Risk
New PS	Roof	4	Poor	3	Moderate	Moderate Risk

Facility	Component	Condition	Condition Rating	Criticality	Criticality Rating	Risk
New PS	Instrumentation	4	Poor	3	Moderate	Moderate Risk
Old PS	Roof	4	Poor	3	Moderate	Moderate Risk
Old PS	Motors	3	Fair	4	High	Moderate Risk
New PS	Pumps	3	Fair	4	High	Moderate Risk
New PS	Motors	3	Fair	4	High	Moderate Risk
Old PS	Alternate Power	2	Good	5	Very High	Moderate Risk
Old PS	HVAC	4	Poor	2	Low	Moderate Risk
Old PS	Valves	4	Poor	2	Low	Moderate Risk
New PS	HVAC	4	Poor	3	Moderate	Moderate Risk
New PS	Valves	4	Poor	2	Low	Moderate Risk
Other	New PS Discharge Meter	4	Poor	2	Low	Moderate Risk
Old PS	Walls	3	Fair	3	Moderate	Moderate Risk
Other	Yard Piping	3	Fair	3	Moderate	Moderate Risk
New PS	Alternate Power	1	Very Good	5	Very High	Moderate Risk
Old PS	Piping	3	Fair	2	Low	Moderate Risk
New PS	Piping	3	Fair	2	Low	Moderate Risk
Other	Tank Overflows	3	Fair	2	Low	Moderate Risk
New PS	Walls	3	Fair	3	Moderate	Moderate Risk
New PS	Foundation	3	Fair	3	Moderate	Moderate Risk
New PS	SCADA	2	Good	3	Moderate	Moderate Risk
Other	Site Drainage	3	Fair	1	Very Low	Low Risk
Other	Entrance Gate	3	Fair	1	Very Low	Low Risk
Other	Video Surveillance	3	Fair	1	Very Low	Low Risk
Old PS	Crane	2	Good	2	Low	Low Risk
New PS	Crane	2	Good	2	Low	Low Risk
Old PS	Instrumentation	2	Good	2	Low	Low Risk
New PS	Chlorine Analyzer	2	Good	2	Low	Low Risk
Other	Fencing	2	Good	2	Low	Low Risk
Old PS	SCADA	1	Very Good	3	Moderate	Low Risk
Old PS	Foundation	1	Very Good	3	Moderate	Low Risk


4.0 FILTERS

Iron and manganese are common in groundwater supplies used by many small water systems. Exceeding the suggested maximum contaminant levels (MCL) usually results in discolored water, laundry, and plumbing fixtures. This, in turn, results in consumer complaints and a general dissatisfaction with the water utility. How iron and manganese are removed depends on the type and concentration and this helps determine the best procedure and (possible) equipment to use.

The City currently does not filter water that comes through the Palm Street Water Plant; however, the City does filter water through the Spring Lake Water Plant to improve water quality. Water quality is typically not a problem at the Palm Street Water Plant, but in the past when the wells have been used exclusively, instead of a blend of TRA supplied surface water and well water, there have been complaints about water quality. FNI has evaluated the site requirements necessary to install filters at the Palm Street Water Plant and determined that there is not space on the site north of Palm St. for the filters but there is space on the site south of Palm St. The anticipated site requirements are 85 ft. by 50 ft. to treat an estimated max flow of 6.07 MGD. To locate the filters on the south side of Palm St. would provide an opportunity to simplify the piping coming into the water plant as well as provide a good site with existing infrastructure (electrical, fencing, access, etc.) for the filters. Figure 1 shows what a filter structure on site would look like.

As discussed in the workshop with the City, it may also be possible to place smaller filtration stations at the individual well sites. This could allow the City to spread out capital expenditures and select the wells with the lowest water quality for filtration rather than filtering all the water. However, adding filters on the discharge of the well pumps will introduce additional headloss which will reduce the capacity of these wells to deliver water to the water plant.

Figure 1: Filters Isometric View



An alternative to filtration would be to add a sequestering agent, such as inorganic polyphosphate. Sequestration is the addition of chemicals to groundwater aimed at controlling problems caused by iron and manganese without removing them. These chemicals are added to groundwater at the well head or at the pump intake before the water has a chance to come in contact with air or chlorine. This ensures that the iron and manganese stays in a soluble form. If the water contains less than 1.0 mg/L iron and less than 0.3 mg/L manganese, using polyphosphates followed by chlorination can be an effective and inexpensive method for mitigating iron and manganese problems. Below these concentrations, the polyphosphates combine with the iron and manganese preventing them from being oxidized.

Further evaluation of the water quality, well sites, and the well pumping capacities would be necessary to determine the feasibility of either option. Figure 2 on the following page shows a potential site for the filters at the Water Plant.




FIGURE 2
CITY OF HUNTSVILLE
FILTERS PLAN

LEGEND

- Proposed Filter Piping
- Proposed Filter Site
- Water Valve
- TRA Water Line
- Well Water Lines
- Water Lines



5.0 RECOMMENDATIONS

5.1 RECOMMENDED IMPROVEMENTS & COST SUMMARY

Each of the components that were determined to have a ‘moderate’ or ‘high’ risk rating and did not receive a ‘very good’ condition rating have been recommended for rehabilitation. In many cases the equipment has been recommended to be completely replaced, when possible repairs have also been recommended. Each of these improvements have been included in the table below with their probable total project costs.

Table 41: Recommended Improvements Summary

Facility	Component	Risk	Recommended Improvement	Opinion of Probable Total Project Cost*
Old PS	MCC	High Risk	Replace New Pump Station MCC	\$246,200
New PS	MCC	High Risk	Replace Old Pump Station MCC	\$420,800
Old PS	Pumps	High Risk	Replace Old Pump Station Pumps	\$172,000
New PS	Roof	Moderate Risk	Repair New Pump Station Roof	\$45,900
New PS	Instrumentation	Moderate Risk	Replace New Pump Station Instrumentation	\$99,500
Old PS	Roof	Moderate Risk	Repair Old Pump Station Roof	\$18,500
Old PS	Motors	Moderate Risk	Replace Old Pump Station Motors	\$75,100
New PS	Pumps	Moderate Risk	Repair/Replace New Pump Station Pumps	\$57,500
New PS	Motors	Moderate Risk	Replace New Pump Station Three Oldest Motors	\$55,600
Old PS	Alternate Power	Moderate Risk	Old Pump Station Alternate Power Improvements	\$23,000
Old PS	HVAC	Moderate Risk	Install Old Pump Station HVAC System	\$22,100
Old PS	Valves	Moderate Risk	Replace Old Pump Station Valves	\$50,400
New PS	HVAC	Moderate Risk	Replace New Pump Station HVAC System	\$32,600
New PS	Valves	Moderate Risk	Replace New Pump Station Valves	\$45,600
Other	New PS Discharge Meter	Moderate Risk	Relocate New Pump Station Discharge Meter and Rework Piping	\$65,700
Old PS	Walls	Moderate Risk	Repair Old Pump Station Walls	\$13,900
Other	Yard Piping	Moderate Risk	Install Isolation Valve on 3.0 MG Ground Storage Tank	\$51,500
Old PS	Piping	Moderate Risk	Replace Old Pump Station Aboveground Piping	\$44,400

Facility	Component	Risk	Recommended Improvement	Opinion of Probable Total Project Cost*
New PS	Piping	Moderate Risk	Replace New Pump Station Aboveground Piping	\$92,400
Other	Tank Overflows	Moderate Risk	Reroute Tank Overflows Away from Apartments	\$80,000
New PS	Walls	Moderate Risk	Repair New Pump Station Walls	\$27,600
New PS	Foundation	Moderate Risk	Repair New Pump Station Foundation	\$10,100
New PS	SCADA	Moderate Risk	Improve New Pump Station SCADA	\$61,200
All	Miscellaneous	Low Risk	Miscellaneous Improvements	\$200,000
Total Project Costs				\$2,011,600

* Cost includes mobilization, contingency, construction management, materials testing and professional services

5.2 SCHEDULE

Since the Palm St. Water Plant supplies the majority of the water to the City of Huntsville, project scheduling will be a critical element to the successful implementation of any rehabilitation project. To be able to reduce the impact to customers it is recommended to time construction during winter months when demand is the lowest. This will allow the pumps to be taken down with minimal impact on the system. FNI has developed three alternatives for scheduling the project. The first alternative is to schedule the electrical repairs/replacements to take place first. Since the MCCs at both of the pump stations are the two highest risk items, addressing those issues first is a good option. Repairs at the old pump station could then take place after the electrical package is complete. Finally the new pump station rehab could take place last since it is generally in better condition than the old pump station.

Table 42: Schedule Alternate 1

Project and Phase	Estimated Duration	OPPC	2016	2017	2018	2019
Electrical Package		\$676,000				
Design	4 months					
Bid	2 months					
Construction	6 months					
Old Pump Station		\$382,000				
Design	4 months					
Bid	2 months					
Construction	8 months					
New Pump Station		\$643,000				
Design	4 months					
Bid	2 months					
Construction	8 months					

Alternative 2 would incorporate the electrical repairs/replacement into each of the pump station packages. This would extend the project duration of each pump station package but reduce the number of construction packages that the City would have to administer. The lengthier construction would have to be well timed to ensure that everything could take place during a low demand season.

Table 43: Schedule Alternate 2

Project and Phase	Estimated Duration	OPCC	2016	2017	2018
Old Pump Station		\$779,000			
Design	6 months				
Bid	2 months				
Construction	10 months				
New Pump Station		\$922,000			
Design	6 months				
Bid	2 months				
Construction	10 months				

Finally, the City could choose to include all of the recommended improvements into one package. The construction may take significantly longer this way as the contractor may need to be under contract through two low demand seasons to be able to complete all the work with the least impact to the users.

Table 44: Schedule Alternate 3

Project and Phase	Estimated Duration	OPCC	2016	2017	2018
Old & New Pump Station					
Design	6 months	\$1,702,100			
Bid	2 months				
Construction	17 months				



6.0 CONSTRUCTION OF A NEW PUMP STATION

Another option available to the City is to construct a new pump station and abandon the two existing pump stations. Since the City is currently on one pressure plane, a dual pump station system is not necessary and potentially better system efficiencies could be realized by combining the pumping into one pump station. This would also provide the City an opportunity to simplify the piping network within the plant and have a pump station that will be completely new, as opposed to two rehabilitated pump stations. It appears that there is sufficient space on the site to the south of Palm St. by the elevated storage tank for a new pump station. Additionally, this would allow for fewer pumps to be installed than the eight that the water plant currently has, which would reduce maintenance costs and time and potentially provide some economy of scale for pump costs. To evaluate what the probable construction cost would be, FNI pulled several recent pump station bids of a similar size (ranging from 4.3 to 20 MGD firm capacity) and developed a trendline to determine what the anticipated cost would be for a 16.5 MGD firm capacity pump station. Using this method FNI estimates that a new 16.5 MGD firm capacity pump station would cost approximately \$4.4 million. This includes a contingency and professional services and is in 2015 dollars.

The figures below shows where the potential pump station could be located and what a 16.5 MGD pump station plan could look like.

Figure 3: New Pump Station Potential Site





NO. ISSUE		BY	DATE	PLAN JOB NO.	OFF14935
				DATE	06/03/14
				DESIGNED	KWW
				DRAWN	MDC
				REVISED	MDC
				CHECKED	KWW
VERIFY SCALE		Bar is one inch on original		FILE NAME	PS_SAMPLE.dwg
0		Drawing on sheet			
		this sheet, adjust scale.			
SHEET		1		Fig. 4	

FREES&NICHOLS

4055 International Plaza, Suite 200
Fort Worth, Texas 76109-4895
Phone (817) 355-5900
Fax (817) 355-5901
Web - www.freese.com



CITY OF HUNTSVILLE

PALM ST. WATER PLANT

NEW PUMP STATION PLAN

Freese and Nichols, Inc.
Texas Registered Engineering Firm F-2144

ACAD: Rel: 19.1s (LWS Tech)
Filename: N:\WTU\PS_SAMPLE.dwg
Last Saved: 6/3/2014 7:28 AM Saved By: mdc



NO.	ISSUE	BY	DATE	PLAN JOB NO.
1				OFF14935
2				DATE 06/03/14
3				DESIGNED KWW
4				DRAWN MDC
5				REVISED MDC
6				CHECKED KWW
7				FILE NAME
8				PS_SAMPLE.dwg

VERIFY SCALE Bar is one inch on original drawing. Adjust on this sheet, adjust scale.

SHEET 2

Fig. 5

CITY OF HUNTSVILLE
PALM ST. WATER PLANT
NEW PUMP STATION SECTION



Freese and Nichols, Inc.
Texas Registered Engineering Firm F-2144

APPENDIX A

CONDITION ASSESSMENT SCORING SHEETS



Palm Street Water Plant (Old Pump Station)



Inspection Date: 5/12/2015

Facility Information:

Date In Service:
Number of Pumps: 4
Total Capacity (gpm): 6,000
Firm Capacity (gpm): 4,000

	<u>Design Point Flow (gpm)</u>	<u>Design Point Head (ft)</u>
Pump 1	1,000	
Pump 2	1,000	
Pump 3	2,000	
Pump 4	2,000	



Condition Scoring Guidelines

1	Very Good condition; no improvements recommended to maintain function
2	Good condition; minor improvements recommended to maintain function
3	Fair condition; improvements recommended to improve performance or efficiency
4	Poor condition; improvements recommended to maintain reliability
5	Very Poor condition; rehabilitation or replacement required

Criticality Scoring Guidelines

1	Very Low impact
2	Low impact
3	Moderate impact
4	High impact
5	Very High impact

Component Group		Component Condition Rating	Component Criticality Rating	Overall Risk Rating	Risk Category	Comments
Electrical	MCC, Switchgear	4	5	9	High	<ul style="list-style-type: none"> Components have been replaced but indications of arc flashes have occurred. Water piping routed through MCC for instrumentation.
	Alternate Power (dual power feed or back up generator)	2	5	7	Moderate	<ul style="list-style-type: none"> Moisture is present in the ATS.
Mechanical	HVAC	4	2	6	Moderate	<ul style="list-style-type: none"> No permanent mechanical ventilation in pump room. Installing one is recommended. Redundant unit heater is recommended.
	Piping	3	2	5	Moderate	<ul style="list-style-type: none"> Original piping from 1960
	Valves	4	2	6	Moderate	<ul style="list-style-type: none"> Gate valves on discharge piping do not turn
Pumps		4	4	8	High	<ul style="list-style-type: none"> Original pump from 1960 High vibration Stuffing box corroded, packing gland studs no longer exist Packing gland not perpendicular to the shaft



Palm Street Water Plant (Old Pump Station)



Inspection Date: 5/12/2015

Facility Information:

Date In Service:
 Number of Pumps: 4
 Total Capacity (gpm): 6,000
 Firm Capacity (gpm): 4,000

	<u>Design Point Flow (gpm)</u>	<u>Design Point Head (ft)</u>
Pump 1	1,000	
Pump 2	1,000	
Pump 3	2,000	
Pump 4	2,000	



Condition Scoring Guidelines

1	Very Good condition; no improvements recommended to maintain function
2	Good condition; minor improvements recommended to maintain function
3	Fair condition; improvements recommended to improve performance or efficiency
4	Poor condition; improvements recommended to maintain reliability
5	Very Poor condition; rehabilitation or replacement required

Criticality Scoring Guidelines

1	Very Low impact
2	Low impact
3	Moderate impact
4	High impact
5	Very High impact

Component Group		Component Condition Rating	Component Criticality Rating	Overall Risk Rating	Risk Category	Comments
Motors		3	4	7	Moderate	• 3 motors are original from 1960
Structure	Crane	2	2	4	Low	• 1.5 ton crane • Would prefer automated crane
	Walls	3	3	6	Moderate	• Cracked Tile • Potential for Asbestos
	Roof	4	3	7	Moderate	• Gutters need to be repaired
	Foundation	1	3	4	Low	
Instrumentation		2	2	4	Low	• Pressure transmitters could be relocated outside of the MCC. • Circular graph charts could be replaced and information could be stored on SCADA
SCADA		1	3	4	Low	



Palm Street Water Plant (New Pump Station)



Inspection Date: 5/12/2015

Facility Information:

Date In Service:
 Number of Pumps: 4
 Total Capacity (gpm): 7,000
 Firm Capacity (gpm): 5,250

	<u>Design Point Flow (gpm)</u>	<u>Design Point Head (ft)</u>
Pump 1	1,750	
Pump 2	1,750	
Pump 3	1,750	
Pump 4	1,750	



Condition Scoring Guidelines

1	Very Good condition; no improvements recommended to maintain function
2	Good condition; minor improvements recommended to maintain function
3	Fair condition; improvements recommended to improve performance or efficiency
4	Poor condition; improvements recommended to maintain reliability
5	Very Poor condition; rehabilitation or replacement required

Criticality Scoring Guidelines

1	Very Low impact
2	Low impact
3	Moderate impact
4	High impact
5	Very High impact

Component Group		Component Condition Rating	Component Criticality Rating	Overall Risk Rating	Risk Category	Comments
Electrical	MCC, Switchgear	4	5	9	High	• Hot spots indicated on starter(s), replacement parts not available
	Alternate Power (dual power feed or back up generator)	1	5	6	Moderate	• New generators have been ordered already
Mechanical	HVAC	4	3	7	Moderate	• Exhaust fan in pump room is near end of useful life, should be replaced, OSHA guards and wall collar added. Unit heater does not work and should be replaced, redundancy is recommended. Electrical room exhaust fan and louver replacement is recommended. Chlorine room needs a wall-mounted unit heater and redundant chlorine sensor. Fluoride room is highly corroded, new fan is needed.
	Piping	3	2	5	Moderate	• Pump 1's piping is corroded where taps have been made
	Valves	4	2	6	Moderate	• BFVs upstream of pump could be replaced with full port valves to improve flow characteristics



Palm Street Water Plant (New Pump Station)



Inspection Date: 5/12/2015

Facility Information:

Date In Service:
 Number of Pumps: 4
 Total Capacity (gpm): 7,000
 Firm Capacity (gpm): 5,250

	<u>Design Point Flow (gpm)</u>	<u>Design Point Head (ft)</u>
Pump 1	1,750	
Pump 2	1,750	
Pump 3	1,750	
Pump 4	1,750	



Condition Scoring Guidelines

1	Very Good condition; no improvements recommended to maintain function
2	Good condition; minor improvements recommended to maintain function
3	Fair condition; improvements recommended to improve performance or efficiency
4	Poor condition; improvements recommended to maintain reliability
5	Very Poor condition; rehabilitation or replacement required

Criticality Scoring Guidelines

1	Very Low impact
2	Low impact
3	Moderate impact
4	High impact
5	Very High impact

Component Group		Component Condition Rating	Component Criticality Rating	Overall Risk Rating	Risk Category	Comments
Pumps		3	4	7	Moderate	<ul style="list-style-type: none"> 3 Pumps have been replaced once before More problematic than the vertical pumps Water lubricated Alignments off
Motors		3	4	7	Moderate	<ul style="list-style-type: none"> 50 hp motors
Structure	Crane	2	2	4	Low	<ul style="list-style-type: none"> 2 ton crane Would prefer automated crane
	Walls	3	3	6	Moderate	<ul style="list-style-type: none"> Insulation damaged Some corrosion around exterior
	Roof	4	3	7	Moderate	<ul style="list-style-type: none"> Insulation damaged Leaking Some corrosion Strap bracing
	Foundation	3	3	6	Moderate	<ul style="list-style-type: none"> Some ponding around exterior Expansion joint repair
Chlorine Analyzer		2	2	4	Low	<ul style="list-style-type: none"> The City would prefer a new chlorine analyzer like the one in the old PS



Palm Street Water Plant (New Pump Station)



Inspection Date: 5/12/2015

Facility Information:

Date In Service:
 Number of Pumps: 4
 Total Capacity (gpm): 7,000
 Firm Capacity (gpm): 5,250

	<u>Design Point Flow (gpm)</u>	<u>Design Point Head (ft)</u>
Pump 1	1,750	
Pump 2	1,750	
Pump 3	1,750	
Pump 4	1,750	



Condition Scoring Guidelines

1	Very Good condition; no improvements recommended to maintain function
2	Good condition; minor improvements recommended to maintain function
3	Fair condition; improvements recommended to improve performance or efficiency
4	Poor condition; improvements recommended to maintain reliability
5	Very Poor condition; rehabilitation or replacement required

Criticality Scoring Guidelines

1	Very Low impact
2	Low impact
3	Moderate impact
4	High impact
5	Very High impact

Component Group	Component Condition Rating	Component Criticality Rating	Overall Risk Rating	Risk Category	Comments
Instrumentation/Controls	4	3	7	Moderate	<ul style="list-style-type: none"> Pressure Switch on Pump 1 not connected MOV control panels have been modified over time an lack documentation.Flow meter is obsolete, replacement parts not available. TRA flow meter is not supported by manufacture, parts are not available.
SCADA	2	3	5	Moderate	<ul style="list-style-type: none"> New SCADA system was recently installed.



Palm Street Water Plant (Other Site Work)



Inspection Date: 5/12/2015



Condition Scoring Guidelines	
1	Very Good condition; no improvements recommended to maintain function
2	Good condition; minor improvements recommended to maintain function
3	Fair condition; improvements recommended to improve performance or efficiency
4	Poor condition; improvements recommended to maintain reliability
5	Very Poor condition; rehabilitation or replacement required

Criticality Scoring Guidelines	
1	Very Low impact
2	Low impact
3	Moderate impact
4	High impact
5	Very High impact

Component Group	Component Condition Rating	Component Criticality Rating	Overall Risk Rating	Risk Category	Comments
Site Drainage	3	1	4	Low	<ul style="list-style-type: none"> Ponding underneath EST Ponding around edges of GSTs
New PS Discharge Meter	4	2	6	Moderate	<ul style="list-style-type: none"> Standard upstream and downstream requirements from flow meter are not being met
Entrance Gate	3	1	4	Low	<ul style="list-style-type: none"> The City would prefer to have an electric rolling gate than the existing swing gate
Video Surveillance	3	1	4	Low	<ul style="list-style-type: none"> No video surveillance of the site, only at the gate
Tank Overflows	3	2	5	Moderate	<ul style="list-style-type: none"> The City would prefer to route overflow away from apartments
Fencing	2	2	4	Low	<ul style="list-style-type: none"> Some barbed wire damaged from storms
Yard Piping	3	3	6	Moderate	<ul style="list-style-type: none"> No isolation valve on line into GST from TRA line BFV at 1.0 MG steel tank hasn't been used since 2007

APPENDIX B DETAILED COST BREAKDOWN

**FREEZE
AND
NICHOLS**Innovative approaches
Practical results
Outstanding service**OPINION OF PROBABLE CONSTRUCTION COSTS**

PROJECT TITLE	Palm St. Water Plant Condition Assessment	DATE	7/31/2015
CLIENT	City of Huntsville	GROUP	1150
SUBMITTAL	Conceptual	PM	Clay Herndon

ESTIMATOR	CHECKED BY	FNI PROJECT NO.
JMB	WCH	HVL15274

ITEM	DESCRIPTION	QUANTITY	UNIT	UNIT PRICE	TOTAL
REPLACE NEW PUMP STATION MCC					
1	MCC Equipment	1	LS	\$ 90,750.00	\$90,750
	Disconnect switches	1	LS	\$ 40,000.00	\$40,000
	Wiring	1	LS	\$ 20,000.00	\$20,000
	Demolition	1	LS	\$ 10,000.00	\$10,000
SUBTOTAL:					\$160,750
MOBILIZATION					5% \$8,100
PROF. SERVICES					12% \$19,300
CMI & MT					6% \$9,700
CONTINGENCY					30% \$48,300
REPLACE NEW PUMP STATION MCC SUBTOTAL:					\$246,200

REPLACE OLD PUMP STATION MCC					
2	MCC Equipment	1	LS	\$ 105,000.00	\$105,000
	Disconnect switches	1	LS	\$ 40,000.00	\$40,000
	New MCC Building	1	LS	\$ 100,000.00	\$100,000
	Wiring	1	LS	\$ 20,000.00	\$20,000
	Demolition	1	LS	\$ 10,000.00	\$10,000
SUBTOTAL:					\$275,000
MOBILIZATION					5% \$13,800
PROF. SERVICES					12% \$33,000
CMI & MT					6% \$16,500
CONTINGENCY					30% \$82,500
REPLACE OLD PUMP STATION MCC SUBTOTAL:					\$420,800

REPLACE OLD PUMP STATION PUMPS					
3	Replace 1,000 gpm pumps	2	EA	\$ 24,750.00	\$49,500
	Replace 2,000 gpm pumps	2	EA	\$ 26,400.00	\$52,800
	Demolition	1	LS	\$ 10,000.00	\$10,000
SUBTOTAL:					\$112,300
MOBILIZATION					5% \$5,700
PROF. SERVICES					12% \$13,500
CMI & MT					6% \$6,800
CONTINGENCY					30% \$33,700
REPLACE OLD PUMP STATION PUMPS SUBTOTAL:					\$172,000

REPAIR NEW PUMP STATION ROOF					
4	Make repairs to fix leaks and repair/replace damaged components	1	LS	\$ 25,000.00	\$25,000
	Demolition	1	LS	\$ 5,000.00	\$5,000
SUBTOTAL:					\$30,000
MOBILIZATION					5% \$1,500
PROF. SERVICES					12% \$3,600
CMI & MT					6% \$1,800
CONTINGENCY					30% \$9,000
REPAIR NEW PUMP STATION ROOF SUBTOTAL:					\$45,900



Innovative approaches
Practical results
Outstanding service

OPINION OF PROBABLE CONSTRUCTION COSTS

PROJECT TITLE	Palm St. Water Plant Condition Assessment	DATE	7/31/2015
CLIENT	City of Huntsville	GROUP	1150
SUBMITTAL	Conceptual	PM	Clay Herndon

ESTIMATOR	CHECKED BY	FNI PROJECT NO.
JMB	WCH	HVL15274

ITEM	DESCRIPTION	QUANTITY	UNIT	UNIT PRICE	TOTAL
REPLACE NEW PUMP STATION INSTRUMENTATION					
5	Valve Actuators	4	EA	\$ 8,000.00	\$32,000
	18" Mag Meter	1	EA	\$ 18,000.00	\$18,000
	Meter Vault	1	EA	\$ 15,000.00	\$15,000
SUBTOTAL:					\$65,000
MOBILIZATION					5% \$3,300
PROF. SERVICES					12% \$7,800
CMI & MT					6% \$3,900
CONTINGENCY					30% \$19,500
REPLACE NEW PUMP STATION INSTRUMENTATION SUBTOTAL:					\$99,500

REPAIR OLD PUMP STATION ROOF					
6	Repair roofing	1	LS	\$ 8,000.00	\$8,000
	Repair cracked/spalled concrete roof slab	1	LS	\$ 1,500.00	\$1,500
	Demolition	1	LS	\$ 2,500.00	\$2,500
SUBTOTAL:					\$12,000
MOBILIZATION					5% \$600
PROF. SERVICES					12% \$1,500
CMI & MT					6% \$800
CONTINGENCY					30% \$3,600
REPAIR OLD PUMP STATION ROOF SUBTOTAL:					\$18,500

REPLACE OLD PUMP STATION MOTORS					
7	Replace pump motors (40 hp)	2	EA	\$ 10,000.00	\$20,000
	Replace pump motors (75 hp)	2	EA	\$ 12,000.00	\$24,000
	Demolition	1	LS	\$ 5,000.00	\$5,000
SUBTOTAL:					\$49,000
MOBILIZATION					5% \$2,500
PROF. SERVICES					12% \$5,900
CMI & MT					6% \$3,000
CONTINGENCY					30% \$14,700
REPLACE OLD PUMP STATION MOTORS SUBTOTAL:					\$75,100

REPAIR/REPLACE NEW PUMP STATION PUMPS					
8	Replace oldest pump	1	EA	\$ 15,000.00	\$15,000
	Rehab newer pumps	2	EA	\$ 10,000.00	\$20,000
	Demolition	1	LS	\$ 2,500.00	\$2,500
SUBTOTAL:					\$37,500
MOBILIZATION					5% \$1,900
PROF. SERVICES					12% \$4,500
CMI & MT					6% \$2,300
CONTINGENCY					30% \$11,300
REPAIR/REPLACE NEW PUMP STATION PUMPS SUBTOTAL:					\$57,500

REPLACE NEW PUMP STATION THREE OLDEST MOTORS					
9	Replace pump motors (50 hp)	3	EA	\$ 10,400.00	\$31,200
	Demolition	1	LS	\$ 5,000.00	\$5,000
SUBTOTAL:					\$36,200
MOBILIZATION					5% \$1,900
PROF. SERVICES					12% \$4,400
CMI & MT					6% \$2,200
CONTINGENCY					30% \$10,900
REPLACE NEW PUMP STATION THREE OLDEST MOTORS SUBTOTAL:					\$55,600



**FREESE
AND
NICHOLS**

Innovative approaches
Practical results
Outstanding service

OPINION OF PROBABLE CONSTRUCTION COSTS

PROJECT TITLE	Palm St. Water Plant Condition Assessment	DATE	7/31/2015
CLIENT	City of Huntsville	GROUP	1150
SUBMITTAL	Conceptual	PM	Clay Herndon

ESTIMATOR	CHECKED BY	FNI PROJECT NO.
JMB	WCH	HVL15274

ITEM	DESCRIPTION	QUANTITY	UNIT	UNIT PRICE	TOTAL
OLD PUMP STATION ALTERNATE POWER IMPROVEMENTS					
10	Reroute conductors and conduits	1	LS	\$ 15,000.00	\$15,000
	SUBTOTAL:				\$15,000
	MOBILIZATION			5%	\$800
	PROF. SERVICES			12%	\$1,800
	CMI & MT			6%	\$900
	CONTINGENCY			30%	\$4,500
	OLD PUMP STATION ALTERNATE POWER IMPROVEMENTS SUBTOTAL:				\$23,000

INSTALL OLD PUMP STATION HVAC SYSTEM					
11	4,000 CFM wall mounted exhaust fan	1	EA	\$ 3,000.00	\$3,000
	3'x4' combination louver damper	1	EA	\$ 1,200.00	\$1,200
	20 MBH gas fired unit heater	2	EA	\$ 2,550.00	\$5,100
	Demolition	1	LS	\$ 5,000.00	\$5,000
	SUBTOTAL:				\$14,300
	MOBILIZATION			5%	\$800
	PROF. SERVICES			12%	\$1,800
	CMI & MT			6%	\$900
	CONTINGENCY			30%	\$4,300
	INSTALL OLD PUMP STATION HVAC SYSTEM SUBTOTAL:				\$22,100

REPLACE OLD PUMP STATION VALVES					
12	Replace 8" Gate Valves	2	EA	\$ 1,500.00	\$3,000
	Replace 12" Gate Valves	2	EA	\$ 2,300.00	\$4,600
	Replace 8" Check Valves	2	EA	\$ 4,000.00	\$8,000
	Replace 12" Check Valves	2	EA	\$ 6,100.00	\$12,200
	Demolition	1	LS	\$ 5,000.00	\$5,000
	SUBTOTAL:				\$32,800
	MOBILIZATION			5%	\$1,700
	PROF. SERVICES			12%	\$4,000
	CMI & MT			6%	\$2,000
	CONTINGENCY			30%	\$9,900
	REPLACE OLD PUMP STATION VALVES SUBTOTAL:				\$50,400

REPLACE NEW PUMP STATION HVAC SYSTEM					
13	4,000 CFM wall mounted exhaust fan	1	EA	\$ 3,000.00	\$3,000
	3'x4' combination louver damper	2	EA	\$ 1,200.00	\$2,400
	5 kW electric unit heater	2	EA	\$ 825.00	\$1,650
	500 CFM roof mounted exhaust fan	2	EA	\$ 1,500.00	\$3,000
	1'x1' combination louver damper	2	EA	\$ 500.00	\$1,000
	3 kW electric unit heater	1	EA	\$ 1,100.00	\$1,100
	Chlorine detector sensor	2	EA	\$ 750.00	\$1,500
	Demolition	1	LS	\$ 7,500.00	\$7,500
	SUBTOTAL:				\$21,150
	MOBILIZATION			5%	\$1,100
	PROF. SERVICES			12%	\$2,600
	CMI & MT			6%	\$1,300
	CONTINGENCY			30%	\$6,400
	REPLACE NEW PUMP STATION HVAC SYSTEM SUBTOTAL:				\$32,600



**FREESE
AND
NICHOLS**

Innovative approaches
Practical results
Outstanding service

OPINION OF PROBABLE CONSTRUCTION COSTS

PROJECT TITLE	Palm St. Water Plant Condition Assessment	DATE	7/31/2015
CLIENT	City of Huntsville	GROUP	1150
SUBMITTAL	Conceptual	PM	Clay Herndon

ESTIMATOR	CHECKED BY	FNI PROJECT NO.
JMB	WCH	HVL15274

ITEM	DESCRIPTION	QUANTITY	UNIT	UNIT PRICE	TOTAL
REPLACE NEW PUMP STATION VALVES					
14	12" Gate Valves	4	EA	\$ 2,300.00	\$9,200
	Replace 12" BFVs with motor operated actuator	3	EA	\$ 6,000.00	\$18,000
	Demolition	1	LS	\$ 2,500.00	\$2,500
SUBTOTAL:					\$29,700
MOBILIZATION					5% \$1,500
PROF. SERVICES					12% \$3,600
CMI & MT					6% \$1,800
CONTINGENCY					30% \$9,000
REPLACE NEW PUMP STATION VALVES SUBTOTAL:					\$45,600

RELOCATE NEW PUMP STATION DISCHARGE METER AND REWORK PIPING					
15	New 12" Ultrasonic Flowmeter	1	EA	\$ 17,825.00	\$17,825
	Flow Meter Vault (assume 6'x5', 6' deep)	4	CY	\$ 600.00	\$2,400
	Flow Meter Vault Cover	1	EA	\$ 800.00	\$800
	12" Steel Water Line	30	LF	\$ 108.00	\$3,240
	12" Steel Fittings	4	EA	\$ 1,500.00	\$6,000
	Concrete Pavement Repair	25	SY	\$ 80.00	\$2,000
	Demo Pavement/Haul Off	1	LS	\$ 1,000.00	\$1,000
	Flow Conditioner	1	EA	\$ 2,000.00	\$2,000
	Demolition	1	LS	\$ 7,500.00	\$7,500
SUBTOTAL:					\$42,765
MOBILIZATION					5% \$2,200
PROF. SERVICES					12% \$5,200
CMI & MT					6% \$2,600
CONTINGENCY					30% \$12,900
RELOCATE NEW PUMP STATION DISCHARGE METER AND REWORK PIPING SUBTOTAL:					\$65,700

REPAIR OLD PUMP STATION WALLS					
16	Replace glazed tile	1	LS	\$ 7,500.00	\$7,500
	Paint	1	LS	\$ 1,500.00	\$1,500
SUBTOTAL:					\$9,000
MOBILIZATION					5% \$500
PROF. SERVICES					12% \$1,100
CMI & MT					6% \$600
CONTINGENCY					30% \$2,700
REPAIR OLD PUMP STATION WALLS SUBTOTAL:					\$13,900

INSTALL ISOLATION VALVE ON 3.0 MG GROUND STORAGE TANK					
17	30" Butterfly Valve	1	EA	\$ 16,000.00	\$16,000
	Excavation and Backfill	1	LS	\$ 10,000.00	\$10,000
	Dewatering	1	LS	\$ 7,500.00	\$7,500
SUBTOTAL:					\$33,500
MOBILIZATION					5% \$1,700
PROF. SERVICES					12% \$4,100
CMI & MT					6% \$2,100
CONTINGENCY					30% \$10,100
INSTALL ISOLATION VALVE ON 3.0 MG GROUND STORAGE TANK SUBTOTAL:					\$51,500

**FREESE
AND
NICHOLS**Innovative approaches
Practical results
Outstanding service**OPINION OF PROBABLE CONSTRUCTION COSTS**

PROJECT TITLE	Palm St. Water Plant Condition Assessment	DATE	7/31/2015
CLIENT	City of Huntsville	GROUP	1150
SUBMITTAL	Conceptual	PM	Clay Herndon

ESTIMATOR	CHECKED BY	FNI PROJECT NO.
JMB	WCH	HVL15274

ITEM	DESCRIPTION	QUANTITY	UNIT	UNIT PRICE	TOTAL
REPLACE OLD PUMP STATION ABOVEGROUND PIPING					
18	8" Ductile Iron Pipe	30	LF	\$ 72.00	\$2,160
	12" Ductile Iron Pipe	30	LF	\$ 108.00	\$3,240
	8" Ductile Iron 45 degree bends	8	EA	\$ 750.00	\$6,000
	12" Ductile Iron 45 degree bends	8	EA	\$ 1,250.00	\$10,000
	Demolition	1	LS	\$ 7,500.00	\$7,500
SUBTOTAL:					\$28,900
MOBILIZATION					5% \$1,500
PROF. SERVICES					12% \$3,500
CMI & MT					6% \$1,800
CONTINGENCY					30% \$8,700
REPLACE OLD PUMP STATION ABOVEGROUND PIPING SUBTOTAL:					\$44,400

REPLACE NEW PUMP STATION ABOVEGROUND PIPING					
19	12" Steel Pipe	80	LF	\$ 108.00	\$8,640
	12" Steel 90 degree bends	8	EA	\$ 1,500.00	\$12,000
	12" Dresser Coupling	4	EA	\$ 2,000.00	\$8,000
	12" Steel Reducers	8	EA	\$ 3,000.00	\$24,000
	Demolition	1	LS	\$ 7,500.00	\$7,500
SUBTOTAL:					\$60,140
MOBILIZATION					5% \$3,100
PROF. SERVICES					12% \$7,300
CMI & MT					6% \$3,700
CONTINGENCY					30% \$18,100
REPLACE NEW PUMP STATION ABOVEGROUND PIPING SUBTOTAL:					\$92,400

REROUTE TANK OVERFLOWS AWAY FROM APARTMENTS					
20	12" Ductile Iron Pipe	330	LF	\$ 108.00	\$35,640
	Outfall Structure	1	LS	\$ 7,500.00	\$7,500
	Ground Water Control	330	LF	\$ 25.00	\$8,250
	Trench Safety	330	LF	\$ 2.00	\$660
SUBTOTAL:					\$52,050
MOBILIZATION					5% \$2,700
PROF. SERVICES					12% \$6,300
CMI & MT					6% \$3,200
CONTINGENCY					30% \$15,700
REROUTE TANK OVERFLOWS AWAY FROM APARTMENTS SUBTOTAL:					\$80,000

REPAIR NEW PUMP STATION WALLS					
21	Make repairs to fix leaks and repair/replace damaged components	1	LS	\$ 14,000.00	\$14,000
	Replace insulation	1	LS	\$ 4,000.00	\$4,000
SUBTOTAL:					\$18,000
MOBILIZATION					5% \$900
PROF. SERVICES					12% \$2,200
CMI & MT					6% \$1,100
CONTINGENCY					30% \$5,400
REPAIR NEW PUMP STATION WALLS SUBTOTAL:					\$27,600



Innovative approaches
Practical results
Outstanding service

OPINION OF PROBABLE CONSTRUCTION COSTS

PROJECT TITLE	Palm St. Water Plant Condition Assessment	DATE	7/31/2015
CLIENT	City of Huntsville	GROUP	1150
SUBMITTAL	Conceptual	PM	Clay Herndon

ESTIMATOR	CHECKED BY	FNI PROJECT NO.
JMB	WCH	HVL15274

ITEM	DESCRIPTION	QUANTITY	UNIT	UNIT PRICE	TOTAL
REPAIR NEW PUMP STATION FOUNDATION					
22	Repair concrete cracks/spalling	90	LF	\$ 50.00	\$4,500
	Seal joints	180	LF	\$ 10.00	\$1,800
	Grout under pipe supports	1	LS	\$ 200.00	\$200
SUBTOTAL:					\$6,500
MOBILIZATION					5% \$400
PROF. SERVICES					12% \$800
CMI & MT					6% \$400
CONTINGENCY					30% \$2,000
REPAIR NEW PUMP STATION FOUNDATION SUBTOTAL:					\$10,100

IMPROVE NEW PUMP STATION SCADA					
23	Adding SCADA capabilities	1	LS	\$ 40,000.00	\$40,000
SUBTOTAL:					\$40,000
MOBILIZATION					5% \$2,000
PROF. SERVICES					12% \$4,800
CMI & MT					6% \$2,400
CONTINGENCY					30% \$12,000
IMPROVE NEW PUMP STATION SCADA SUBTOTAL:					\$61,200


MISCELLANEOUS IMPROVEMENTS					
24	Site/Civil Improvements, Buried Valves, and Other Infrastructure	1	LS	\$ 200,000.00	\$200,000
MISCELLANEOUS IMPROVEMENTS SUBTOTAL:					\$200,000

PROJECT TOTAL					\$2,011,600
---------------	--	--	--	--	-------------

NOTES:

- Costs shown are in 2015 Dollars
- Buried infrastructure such as valves and pipin were not investigated as part of this condition assessment.

APPENDIX C
SMITH PUMP CO. PUMP ASSESSMENT



PALM STREET WATER PLANT, BOOSTER PUMP STATION FIELD CONDITION ASSESSMENT

OWNER: CITY OF HUNTSVILLE

ENGINEER: FREESE & NICHOLS

PUMP STATIONS: OLD BOOSTER P.S.
NEW BOOSTER P.S.



EXECUTIVE SUMMARY

BRIEF REVIEW OF PUMP STATIONS AND RESULTS

EXECUTIVE SUMMARY

BACKGROUND

Charged with documenting the condition of the booster pumps and motors for the City of Houston, Smith Pump Co. inspected eight (8) pumps. From our inspections we can characterize the condition of each unit and make some generalizations about needed repair/maintenance.

This summary will briefly describe the observations made during testing for each unit. This includes mechanical soundness and hydraulic performance. To rate each category we will use a five point scale. In order from best to worst these points are... Good, Fair, Ok, Below Average, Poor. Below you will also find our determination on whether to repair or replace.

OLD BOOSTER P.S., BP-1

Description

The pump tested is a Layne 12WMC vertical turbine pump with a US Motors vertical induction motor. This pump has a heavy gage steel coupling guard that could not be removed, therefore shaft and packing conditions could not be observed.

Hydraulic Performance

The hydraulic performance appears to match the pump curve provided by the city. The data points seem unrealistic when taking into account the number of years since the previous repair. This can possibly be explained by the non-ideal placement of the flow meter giving higher than expected readings.

Mechanical Inspection

Mechanically, BP-1 is in "Below Average" condition. Inspection of this pump is for the discharge head and motor only.

- The discharge head appears to be in good condition
- The coupling guard should be replaced with something easier to remove in order to allow access to adjust the packing
- The highest vibration reading of **0.918** in/sec rms, or seven (7) times higher than the HI limit, was recorded at the top of the motor
- This unit should only be run if absolutely necessary due to the excessive vibration

Other Observations

N/A

Recommendations

This pump could not be inspected below the barrel flange, but with the high vibration it is recommended that this unit be pulled, disassembled, and inspected.

OLD BOOSTER P.S., BP-2***Description***

The pump tested is a Layne 12WMC vertical turbine pump with a US Motors vertical induction motor. This pump has a heavy gage steel coupling guard that could not be removed, therefore shaft and packing conditions could not be observed.

Hydraulic Performance

The hydraulic performance appears to be slightly better than the pump curve provided by the city. The data points seem unrealistic when taking into account the number of years since the previous repair. This can possibly be explained by the non-ideal placement of the flow meter giving higher than expected readings.

Mechanical Inspection

Mechanically, BP-2 is in "Below Average" condition. Inspection of this pump is for the discharge head and motor only.

- The discharge head appears to be in good condition
- The coupling guard should be replaced with something easier to remove in order to allow access to adjust the packing
- The highest vibration reading of **0.297** in/sec rms, or two (2) times higher than the HI limit, was recorded at the top of the motor

Other Observations

N/A

Recommendations

This pump could not be inspected below the barrel flange, but with the high vibration it is recommended that this unit be pulled, disassembled, and inspected.

OLD BOOSTER P.S., BP-3***Description***

The pump tested is a Layne 12THC vertical turbine pump with a US Motors vertical induction motor.

Hydraulic Performance

The hydraulic performance appears to be slightly better than the pump curve provided by the city. The data points seem unrealistic when taking into account the number of years since the previous repair. This can possibly be explained by the non-ideal placement of the flow meter giving higher than expected readings.

Mechanical Inspection

Mechanically, BP-3 is in "OK" condition. Inspection of this pump is for the discharge head, stuffing box, motor shaft, and motor only.

- The discharge head appears to be in good condition
- The stuffing box is severely corroded and it appears as if the packing gland studs no longer exist
- The packing gland was not perpendicular to the shaft
- The highest vibration reading of **0.189** in/sec rms, or slightly higher than the HI limit, was recorded at the top of the motor

Other Observations

N/A

Recommendations

This pump could not be inspected below the barrel flange, but with the slightly higher vibration it is recommended that this unit be field balanced in an attempt to reduce the vibration.

OLD BOOSTER P.S., BP-4***Description***

The pump tested is a Layne 12THC vertical turbine pump with a US Motors vertical induction motor.

Hydraulic Performance

The hydraulic performance appears to be slightly better than the pump curve provided by the city. The data points seem unrealistic when taking into account the number of years since the previous repair. This can possibly be explained by the non-ideal placement of the flow meter giving higher than expected readings.

Mechanical Inspection

Mechanically, BP-4 is in "Poor" condition. Inspection of this pump is for the discharge head, stuffing box, motor shaft, and motor only.

- The discharge head appears to be in good condition

- The stuffing box is severely corroded and it appears as if the packing gland studs no longer exist
- The packing gland was not perpendicular to the shaft
- The highest vibration reading of **0.383** in/sec rms, or 2.5 times higher than the HI limit, was recorded at the top of the motor

Other Observations

N/A

Recommendations

This pump could not be inspected below the barrel flange, but with the high vibration it is recommended that this unit be pulled, disassembled, and inspected.

NEW BOOSTER P.S. BP-1***Description***

The pump tested is a Goulds 3405 6x8-12 horizontal split case pump with a Siemens horizontal induction motor.

Hydraulic Performance

The pump matches the pump curve very closely and appears to be 6 ft TDH low. The efficiency is approximately 10 percentage points low.

Mechanical Inspection

Mechanically, BP-1 is in "Good" condition.

- The efficiency is a little low and is likely caused by excessive wear ring clearance
- The pump has very low vibration, maximum was 0.076 in/sec rms
- The alignment is severely off and motor would be bolt bound

Other Observations

The suction piping configuration does not follow HI standards. An eccentric reducer is located too close to the suction of the pump.

Recommendations

This pump has low vibration and can be run. The alignment should be corrected.

NEW BOOSTER P.S. BP-2

Description

The pump tested is a Goulds 3405 6x8-12 horizontal split case pump with a Siemens horizontal induction motor.

Hydraulic Performance

Hydraulic performance cannot be determined as neither the city nor the manufacture has been able to locate a curve.

Mechanical Inspection

Mechanically, BP-2 is in "Good" condition.

- The pump has very low vibration, maximum was 0.052 in/sec rms
- The alignment is off and appears to be easily corrected

Other Observations

The suction piping configuration does not follow HI standards. An eccentric reducer is located too close to the suction of the pump.

Recommendations

This pump has low vibration and can be run. The alignment should be corrected.

NEW BOOSTER P.S. BP-3

Description

The pump tested is a Goulds 3405 6x8-12 horizontal split case pump with a Power Tech horizontal induction motor.

Hydraulic Performance

Hydraulic performance cannot be determined as neither the city nor the manufacture has been able to locate a curve.

Mechanical Inspection

Mechanically, BP-3 is in "OK" condition.

- The pump has very low vibration, maximum was 0.028 in/sec rms
- The motor has high vibration, maximum was 0.153 in/sec rms, but isn't severe
- The alignment is off and appears to be easily corrected

Other Observations

The suction piping configuration does not follow HI standards. An eccentric reducer is located too close to the suction of the pump.

Recommendations

This motor has slightly high vibration but can be run. The alignment should be corrected and may bring the motor vibration under the HI limit.

NEW BOOSTER P.S. BP-4***Description***

The pump tested is a Goulds 3405 6x8-12 horizontal split case pump with a Siemens horizontal induction motor.

Hydraulic Performance

Hydraulic performance cannot be determined as neither the city nor the manufacture has been able to locate a curve.

Mechanical Inspection

Mechanically, BP-4 is in "OK" condition.

- The pump vibration is close to the HI limit, maximum was 0.139 in/sec rms
- The alignment is severely off but the motor feet are already directly on the motor pad and cannot be lowered any more

Other Observations

The suction piping configuration does not follow HI standards. An eccentric reducer is located too close to the suction of the pump.

Recommendations

This pump has slightly high vibration and can be run. The alignment needs to be corrected, which may require shimming the pump. This not the preferred setup and may increase the vibration level.

REPORT OUTLINE

<u>ITEM</u>	<u>PAGE</u>	<u>DESCRIPTION</u>
1	1	<u>COVER PAGE</u>
2	2	<u>EXECUTIVE SUMMARY</u>
3	9	<u>REPORT OUTLINE</u>
4	10	<u>PUMP EVALUATION PROCEDURE</u>
5	15	<u>OLD BOOSTER PUMP STATION</u>
6	16	OLD BOOSTER PS, BP-1
7	22	OLD BOOSTER PS, BP-2
8	28	OLD BOOSTER PS, BP-3
9	34	OLD BOOSTER PS, BP-4
10	41	<u>NEW BOOSTER PUMP STATION</u>
11	42	NEW BOOSTER PS, BP-1
12	51	NEW BOOSTER PS, BP-2
13	57	NEW BOOSTER PS, BP-3
14	64	NEW BOOSTER PS, BP-4
15	71	<u>APPENDICES</u>



PUMP EVALUATION PROCEDURE

HYDRAULIC TEST PROCEDURE

OBJECTIVE

The objective is to measure certain parameters of the pumps and motors in the field to determine the condition, and degree of wear of the equipment.

TYPE OF TESTS

Smith Pump Co. measured the flow, head, speed, input power, and vibration for eight (8) pumps. The pumps were allowed to operate normally into the system and two (2) sets of data were taken ten to fifteen minutes apart to ensure consistent data.

VIBRATION LIMITS

For vertical turbine pumps, the vibration is measured at five (5) locations, three (3) locations at the top of the motor and two (2) locations on the bottom flange of the motor. If the Hydraulic Institute Standard 9.6.4 (2009) applies, the unfiltered vibration amplitude limit is 0.13 in/sec rms at any speed within the Preferred Operating Range (POR) and 0.17 in/sec rms at any speed within the Allowable Operating Range (AOR) but outside the POR.

For horizontal split case pumps, the vibration is measured at ten (10) locations; three (3) locations on the opposite drive end motor bearing, two (2) locations on the drive end motor bearing, two (2) locations on the drive end pump bearing, and three (3) locations on the opposite drive end pump bearing. If the HIS 9.6.4 (2009) applies, the unfiltered vibration amplitude limit is 0.15 in/sec rms at any speed within the POR and 0.20 in/sec rms at any speed within the AOR but outside the POR.

PIPING ARRANGEMENT

The suction and discharge headers will be 100% open while gathering performance test data.

PERFORMANCE TEST PROCEDURE

Prior to starting the performance test:

- Check that all instruments are within their calibration period
- Proper position of valves will be verified
- Pressure gages will be place on the suction and discharge pipe
- Portable flow meter will be place on longest run of straight pipe
- The motor will be run at full speed
- The flow will be allowed to stabilize
- After 10 minutes, record first set of data
 - Measure flow and pressure close to the same time
 - Measure voltage, current, and power factor or input kilowatts

- Measure vibration
- After 25 minutes, record second set of data
 - See above

INSTRUMENTATION

The following instrumentation was used:

-Flow GE Panametrics PT878 Ultrasonic Portable Flow Meter. S/N: 02368 (Vertical Turbine Pumps)

City of Huntsville's Accumulation Flow Meter (Horizontal Split Case Pumps)



Figure 1: GE Panametrics PT878

-Suction Pressure Ashcroft 1082 150 mm combination test quality pressure gauge. Gauge No. TGC-7101. Set to read pressure on a scale of 0 to 30 psig positive and 0 to 30 in Hg of vacuum.

-Disch. Pressure Ashcroft 1082 150 mm combination test quality pressure gauge. Gauge No. E219115. Set to read pressure on a scale of 0 to 460 ft of H₂O

-Speed Pruftechnik VibeScanner Data Analyzer type VIB 5.480-P. S/N: 03642

-Power Extech True RMS Power Meter type 380976-K. S/N: 120210916

-Vibration Pruftechnik VibeScanner Data Analyzer type VIB 5.480-P. S/N: 03642



Figure 2: VibXpert VIB 5.480-P

TEST RESULTS

HEAD

- As a function of flow is determined by calculation of the total dynamic head

PUMP BRAKE HORSEPOWER

- As a function of flow is independently measured from Smith Pump's Extech True RMS Power Meter

EFFICIENCY

- As a function of flow is calculated from the pump brake horsepower

VIBRATION MEASUREMENT LOCATIONS***VERTICAL TURBINE PUMP***

MT = Motor top

MB = Motor bottom

MV = Motor in the vertical direction

0 = In line with the discharge

90 = 90° to discharge

For example, MT-90 is a data point taken at the top of the motor and perpendicular to the discharge.

HORIZONTAL SPLIT CASE PUMP

ODE = Opposite Drive End

DE = Drive End

X = Perpendicular to the shaft and parallel to the floor

Y = Perpendicular to the shaft and the floor

Z = In the direction of the shaft

For example, Motor ODE-X is a data point taken on the opposite drive end of the motor in the X direction.

FIELD INSPECTION PROCEDURE (VERTICAL TURBINE PUMPS)

NOT APPLICABLE

FIELD INSPECTION PROCEDURE (HORIZONTAL SPLIT CASE PUMP)**OBJECTIVE**

Determine whether the pump is aligned to the motor.

TYPE OF TESTS

Smith Pump Co. pump servicemen to record alignment with an Aligneo laser alignment.

INSTRUMENTATION

The following instrumentation was used:

-Alignment Ludeca Aligneo,
Model ALI 11.100.
Transducer S/N:
1207 1272, Prism
S/N: 1407 9959



Figure 3: Ludeca Aligneo



OLD BOOSTER PUMP STATION

FIELD PERFORMANCE TEST REPORT

GENERAL ARRANGEMENT

This station has four (4) vertical turbine pumps. Booster pump #1 and #2 are Layne 12WMC pumps with 40 hp vertical hollow shaft motors. Booster pumps #3 and #4 are Layne 12THC pumps with 75 hp vertical hollow shaft motors.

PERFORMANCE TESTING VARIANCES

None

BOOSTER PUMP #1

HYDRAULIC PERFORMANCE TESTING

TEST RESULTS

The composite curve below, Figure 4, shows the field data plotted with the curve provided by the city.

The pump performance test data (hydraulic and electrical) shows the two (2) field test points are shown in the same color as each curve. The instrument values are recorded in concert with one another. The data is reduced to result in the points that show up in the composite curve chart. The data is speed corrected to the catalog curve test speed so that the test data can be compared.

Winding and bearing temperatures could not be recorded as there were not any displays for this data.




Figure 4: Old Booster Pump Station, Booster Pump #1 Field Performance Curve

Below are the vibration readings recorded on this pump:

UNFILTERED VIBRATION READINGS		
Location	Reading (in/sec rms)	Below HI Limits?
MT-0	0.918	No
	0.885	No
MT-90	0.359	No
	0.357	No
MT-V	0.085	Yes
	0.083	Yes
MB-0	0.707	No
	0.684	No
MB-90	0.221	No
	0.238	No




Figure 5: MT-90 Bump Test, Reed Frequency at 1,424 cpm, Motor Speed is 1,785 rpm




Figure 6: MT-0 Bump Test, Reed Frequency at 1,789 cpm, Motor Speed is 1,785 rpm




Figure 7: MT-90 Filtered Vibration, highest peak is 0.346 in/sec rms at 1,788 cpm (1X run speed)




Figure 8: MT-0 Filtered Vibration, highest peak is 0.863 in/sec at 1,788 cpm (1X run speed)




Figure 9: MT-V Filtered Vibration, highest peak is 0.074 in/sec at 1,788 cpm (1X run speed) and the next highest peak is 0.016 in/sec at 3,574 cpm (2X run speed)




Figure 10: MB-90 Filtered Vibration, highest peak is 0.223 in/sec at 1,788 cpm (1X run speed), the next peak is 0.014 in/sec at 7,148 cpm (4X run speed)




Figure 11: MB-0 Filtered Vibration, highest peak is 0.675 in/sec at 1,788 cpm (1X run speed)

The reed frequency, as shown in Figures 5, is at 1,424 cpm 90 degrees to discharge which is 20% from run speed and should not cause any issues. The reed frequency, as shown in Figure 6, is at 1,789 cpm which is at run speed and will exacerbate and amplify any vibration.

The vibration at all of the locations has a dominant peak at 1X run speed. This is a typical signature of rotating equipment and indicates a slight imbalance and/or misalignment or looseness. The amplitude is very high at all locations, except for the vertical direction, and should be corrected. Field balancing may resolve the issue but it may be caused by loose pump bearings which would require the pump to be pulled and repaired

TEST DISCUSSIONS

HYDRAULIC OPERATION

- The hydraulic performance appears to match the pump curve provided by the city. The data points seem unrealistic when taking into account the number of years since the previous repair.

ELECTRICAL OPERATION

- Voltage and current were measured using Smith Pump's Extech True RMS Power Meter

- During the test, a maximum current of 34 amps was recorded which is less than the full load amps of this motor

MECHANICAL OPERATION

- Pump vibration is above the Hydraulic Institute Standards with the highest vibration being 0.918 in/sec rms
- Pump should not be run unless absolutely necessary

BOOSTER PUMP #2

HYDRAULIC PERFORMANCE TESTING

TEST RESULTS

The composite curve below, Figure 12, shows the field data plotted with the curve provided by the city.

The pump performance test data (hydraulic and electrical) shows the two (2) field test points are shown in the same color as each curve. The instrument values are recorded in concert with one another. The data is reduced to result in the points that show up in the composite curve chart. The data is speed corrected to the catalog curve test speed so that the test data can be compared.

Winding and bearing temperatures could not be recorded as there were not any displays for this data.




Figure 12: Old Booster Pump Station, Booster Pump #2 Field Performance Curve

Below are the vibration readings recorded on this pump:

UNFILTERED VIBRATION READINGS		
Location	Reading (in/sec rms)	Below HI Limits?
MT-0	0.281	No
	0.297	No
MT-90	0.070	Yes
	0.068	Yes
MT-V	0.043	Yes
	0.043	Yes
MB-0	0.224	No
	0.225	No
MB-90	0.046	Yes
	0.047	Yes




Figure 13: MT-90 Bump Test, Reed Frequency at 1,420 cpm, Motor Speed is 1,785 rpm




Figure 14: MT-0 Bump Test, Reed Frequency at 1,790 cpm, Motor Speed is 1,785 rpm




Figure 15: MT-90 Filtered Vibration, highest peak is 0.065 in/sec rms at 1,785 cpm (1X run speed)




Figure 16: MT-0 Filtered Vibration, highest peak is 0.286 in/sec at 1,785 cpm (1X run speed) and the next highest peak is 0.017 in/sec at 7,196 cpm (4X run speed)




Figure 17: MT-V Filtered Vibration, highest peak is 0.029 in/sec at 1,785 cpm (1X run speed) and the next highest peak is 0.021 in/sec at 14,291 cpm (8X run speed)




Figure 18: MB-90 Filtered Vibration, highest peak is 0.040 in/sec at 1,785 cpm (1X run speed)




Figure 19: MB-0 Filtered Vibration, highest peak is 0.219 in/sec at 1,785 cpm (1X run speed) and the next highest peak is 0.025 in/sec at 7,200 cpm (4X run speed)

The reed frequency, as shown in Figures 13, is at 1,420 cpm 90 degrees to discharge which is 20% from run speed and should not cause any issues. The reed frequency, as shown in Figure 14, is at 1,790 cpm which is at run speed and will exacerbate and amplify any vibration.

The vibration at all of the locations has a dominant peak at 1X run speed. This is a typical signature of rotating equipment and indicates a slight imbalance and/or misalignment or looseness. The amplitude is very high at the locations that are in-line with the discharge and should be corrected. Field balancing may resolve the issue but it may be caused by loose pump bearings which would require the pump to be pulled and repaired

TEST DISCUSSIONS

HYDRAULIC OPERATION

- The pump appears to outperform the pump curve provided by the city. The data points seem unrealistic when taking into account the number of years since the previous repair.

ELECTRICAL OPERATION

- Voltage and current were measured using Smith Pump's Extech True RMS Power Meter

- During the test, a maximum current of 33 amps was recorded which is less than the full load amps of this motor

MECHANICAL OPERATION

- Pump vibration is above the Hydraulic Institute Standards with the highest vibration being 0.297 in/sec rms
- Pump runtime should be kept to a minimum

BOOSTER PUMP #3

HYDRAULIC PERFORMANCE TESTING

TEST RESULTS

The composite curve below, Figure 20, shows the field data plotted with the curve provided by the city.

The pump performance test data (hydraulic and electrical) shows the two (2) field test points are shown in the same color as each curve. The instrument values are recorded in concert with one another. The data is reduced to result in the points that show up in the composite curve chart. The data is speed corrected to the catalog curve test speed so that the test data can be compared.

Winding and bearing temperatures could not be recorded as there were not any displays for this data.




Figure 20: Old Booster Pump Station, Booster Pump #3 Field Performance Curve

Below are the vibration readings recorded on this pump:

UNFILTERED VIBRATION READINGS		
Location	Reading (in/sec rms)	Below HI Limits?
MT-0	0.181	No
	0.189	No
MT-90	0.061	Yes
	0.080	Yes
MT-V	0.048	Yes
	0.037	Yes
MB-0	0.084	Yes
	0.129	Yes
MB-90	0.034	Yes
	0.036	Yes




Figure 21: MT-90 Bump Test, Reed Frequency at 1,002 cpm, Motor Speed is 1,785 rpm




Figure 22: MT-0 Bump Test, Reed Frequency at 1,291 cpm, Motor Speed is 1,785 rpm. The highest peak is from the sister unit running while this unit was being bump tested.




Figure 23: MT-90 Filtered Vibration, highest peak is 0.042 in/sec rms at 1,792 cpm (1X run speed)




Figure 24: MT-0 Filtered Vibration, highest peak is 0.149 in/sec at 1,792 cpm (1X run speed)




Figure 25: MT-V Filtered Vibration, all data is below 0.020 in/sec




Figure 26: MB-90 Filtered Vibration, all data is below 0.020 in/sec




Figure 27: MB-0 Filtered Vibration, highest peak is 0.082 in/sec at 1,792 cpm (1X run speed)

The reed frequency, as shown in Figures 21, is at 1,002 cpm 90 degrees to discharge which is 44% from run speed and should not cause any issues. The reed frequency, as shown in Figure 22, is at 1,291 cpm which is 28% from run speed and should not cause any issues.

The vibration at all of the locations has a dominant peak at 1X run speed. This is a typical signature of rotating equipment and indicates a slight imbalance and/or misalignment or looseness. The amplitude for the most part is low but the vibration at the top of the motor in-line with the discharge is slightly above the HI limits. Field balancing would likely resolve this issue.

TEST DISCUSSIONS

HYDRAULIC OPERATION

- The pump appears to outperform the catalog curve provided by the city. The data points seem unrealistic when taking into account the number of years since the previous repair.

ELECTRICAL OPERATION

- Voltage and current were measured using Smith Pump's Extech True RMS Power Meter
- During the test, a maximum current of 81 amps was recorded which is less than the full load amps of this motor

MECHANICAL OPERATION

- Pump vibration is slightly above the Hydraulic Institute Standards with the highest vibration being 0.189 in/sec rms
- There are no foreseeable issues with running this pump as-is.

BOOSTER PUMP #4

HYDRAULIC PERFORMANCE TESTING

TEST RESULTS

The composite curve below, Figure 28, shows the field data plotted with the curve provided by the city.

The pump performance test data (hydraulic and electrical) shows the two (2) field test points are shown in the same color as each curve. The instrument values are recorded in concert with one another. The data is reduced to result in the points that show up in the composite curve chart. The data is speed corrected to the catalog curve test speed so that the test data can be compared.

Winding and bearing temperatures could not be recorded as there were not any displays for this data.




Figure 28: Old Booster Pump Station, Booster Pump #4 Field Performance Curve

Below are the vibration readings recorded on this pump:

UNFILTERED VIBRATION READINGS		
Location	Reading (in/sec rms)	Below HI Limits?
MT-0	0.371	No
	0.383	No
MT-90	0.328	No
	0.298	No
MT-V	0.103	Yes
	0.099	Yes
MB-0	0.246	No
	0.255	No
MB-90	0.184	No
	0.171	No




Figure 29: MT-90 Bump Test, Reed Frequency at 1,095 cpm, Motor Speed is 1,785 rpm




Figure 30: MT-0 Bump Test, Reed Frequency at 1,243 cpm, Motor Speed is 1,785 rpm




Figure 31: MT-90 Filtered Vibration, highest peak is 0.307 in/sec rms at 1,785 cpm (1X run speed)




Figure 32: MT-0 Filtered Vibration, highest peak is 0.392 in/sec at 1,785 cpm (1X run speed)




Figure 33: MT-V Filtered Vibration, highest peak is 0.084 in/sec at 1,785 cpm (1X run speed)




Figure 34: MB-90 Filtered Vibration, highest peak is 0.171 in/sec at 1,785 cpm (1X run speed)




Figure 35: MB-0 Filtered Vibration, highest peak is 0.238 in/sec at 1,785 cpm (1X run speed) and the second highest peak is 0.046 in/sec at 5,358 cpm

The reed frequency, as shown in Figures 29, is at 1,095 cpm 90 degrees to discharge which is 39% from run speed and should not cause any issues. The reed frequency, as shown in Figure 30, is at 1,243 cpm which is 30% from run speed and should not cause any issues.

The vibration at all of the locations has a dominant peak at 1X run speed. This is a typical signature of rotating equipment and indicates a slight imbalance and/or misalignment or looseness. The amplitude is very high at the locations that are in-line and 90 degree to the discharge and should be corrected. Field balancing may resolve the issue but it is more likely caused by loose pump bearings which would require the pump to be pulled and repaired

TEST DISCUSSIONS

HYDRAULIC OPERATION

- The pump appears to outperform the catalog curve provided by the city. The data points seem unrealistic when taking into account the number of years since the previous repair.

ELECTRICAL OPERATION

- Voltage and current were measured using Smith Pump's Extech True RMS Power Meter

- During the test, a maximum current of 68 amps was recorded which is less than the full load amps of this motor

MECHANICAL OPERATION

- Pump vibration is well above the Hydraulic Institute Standards with the highest vibration being 0.383 in/sec rms
- This pump's runtime should be kept to a minimum



NEW BOOSTER PUMP STATION

FIELD PERFORMANCE TEST REPORT

GENERAL ARRANGEMENT

This station has four (4) horizontal split case pumps. All of the pumps are the same size. The pumps are Goulds 3405 6x8-12 horizontal split case pump with three (3) Siemens and one (1) Power Tech horizontal induction motors.

PERFORMANCE TESTING VARIANCES

None

BOOSTER PUMP #1

HYDRAULIC PERFORMANCE TESTING

TEST RESULTS

The pump performance test data (hydraulic) shows the two (2) field test points recorded for each pump, shown with circles, and the catalog curve. The instrument values are recorded in concert with one another. The data is reduced to result in the points that show up in the composite curve chart in Figure 36 below. The data is speed corrected to the catalog curve test speed so that the test data can be compared.

Winding and bearing temperatures could not be recorded as there were not any displays for this data.




Figure 36: New Booster PS, Booster Pump #1 Field Performance Curve

Below are the vibration readings recorded on this pump:

UNFILTERED VIBRATION READINGS			
Location		Reading (in/sec rms)	Below HI Limits?
MOTOR	ODE-X	0.044	Yes
		0.037	Yes
	ODE-Y	0.055	Yes
		0.066	Yes
	ODE-Z	0.067	Yes
		0.057	Yes
	DE-X	0.076	Yes
		0.072	Yes
	DE-Y	0.043	Yes
		0.041	Yes

PUMP	DE-X	0.034	Yes
		0.038	Yes
	DE-Y	0.026	Yes
		0.028	Yes
	ODE-X	0.021	Yes
		0.020	Yes
	ODE-Y	0.014	Yes
		0.014	Yes
	ODE-Z	0.031	Yes
		0.030	Yes




Figure 37: Motor ODE-Y Filtered Vibration, highest peak is 0.060 in/sec at 1,766 cpm (1X run speed)




Figure 38: Motor ODE-X Filtered Vibration, highest peak is 0.024 in/sec at 7,200 cpm (1X run speed) with other peaks at 1,766 cpm (1X run speed) and 3,536 cpm (2X run speed)




Figure 39: Motor ODE-Z Filtered Vibration, highest peak is 0.053 in/sec at 1,785 cpm (1X run speed)




Figure 40: Motor DE-Y Filtered Vibration, highest peak is 0.022 in/sec at 1,766 cpm (1X run speed) with a smaller peak at 7,200 cpm (electrical frequency)




Figure 41: Motor DE-X Filtered Vibration, highest peak is 0.053 in/sec at 1,766 cpm (1X run speed) with a smaller peak at 3,536 cpm (2X run speed) and 7,200 cpm (electrical frequency)




Figure 42: Pump DE-Y Filtered Vibration, highest peak is 0.020 in/sec at 1,766 cpm (1X run speed)




Figure 43: Pump DE-X Filtered Vibration, highest peak is 0.027 in/sec at 1,766 cpm (1X run speed) with a smaller peak at 10,601 cpm (6X run speed)




Figure 44: Pump ODE-Y Filtered Vibration, all peaks are below 0.005 in/sec




Figure 45: Pump ODE-X Filtered Vibration, all peaks are below 0.010 in/sec




Figure 46: Pump ODE-Z Filtered Vibration, all peaks are below 0.010 in/sec

The motor and pump vibration are very low at all locations.

TEST DISCUSSIONS

HYDRAULIC OPERATION

- The pump matches the catalog curve provided by the manufacturer.
- The total dynamic head is approximately 3 ft low
- The efficiency is approximately 11 percentage points low

ELECTRICAL OPERATION

- Voltage and current were measured using Smith Pump's Extech True RMS Power Meter
- During the test, a maximum current of 66 amps was recorded which is more than the full load amps of this motor and should be monitored
- The pump overloads the motor but it is likely caused by only one pump running instead of two

MECHANICAL OPERATION

- Pump vibration is well below the Hydraulic Institute Standards with the highest vibration being 0.076 in/sec rms
- This pump is running very well

FIELD INSPECTION

TEST RESULTS

The alignment between the pump and motor shaft was measured. The vertical offset misalignment is 0.0078" and the angular misalignment is 0.0193". The horizontal offset misalignment is 0.0348" and the angular misalignment is 0.1212". The motor cannot be repositioned to align to the pump because the motor bolt holes do not have enough slack.

OTHER OBSERVATIONS

The eccentric reducer on the suction side of the pump is located too close to the pump, see Figure 47. This reducer should be positioned farther from the pump to ensure no cavitation or hydraulic issues.



Figure 47: Suction Piping of Booster Pump #1

BOOSTER PUMP #2

HYDRAULIC PERFORMANCE TESTING

TEST RESULTS

The coupling on the discharge piping was to be used for the discharge gage. The discharge and suction valves were closed but the pressure could not be relieved. The plug in the coupling could not be pulled because the valves would not seal off the pressure.

Below are the vibration readings recorded on this pump:

UNFILTERED VIBRATION READINGS			
Location		Reading (in/sec rms)	Below HI Limits?
MOTOR	ODE-X	0.025	Yes
	ODE-Y	0.025	Yes
	ODE-Z	0.022	Yes
	DE-X	0.052	Yes
	DE-Y	0.050	Yes
PUMP	DE-X	0.029	Yes
	DE-Y	0.019	Yes
	ODE-X	0.021	Yes
	ODE-Y	0.020	Yes
	ODE-Z	0.027	Yes




Figure 48: Motor ODE-Y Filtered Vibration, all peaks are below 0.015 in/sec




Figure 49: Motor ODE-X Filtered Vibration, all peaks are below 0.015 in/sec




Figure 50: Motor ODE-Z Filtered Vibration, all peaks are below 0.010 in/sec




Figure 51: Motor DE-Y Filtered Vibration, highest peak is 0.034 in/sec at 1,778 cpm (1X run speed) with the remaining peaks below 0.015 in/sec




Figure 52: Motor DE-X Filtered Vibration, highest peak is 0.041 in/sec at 1,778 cpm (1X run speed) with the remaining peaks below 0.010 in/sec




Figure 53: Pump DE-Y Filtered Vibration, all peaks are below 0.010 in/sec




Figure 54: Pump DE-X Filtered Vibration, all peaks are below 0.010 in/sec




Figure 55: Pump ODE-Y Filtered Vibration, all peaks are below 0.015 in/sec




Figure 56: Pump ODE-X Filtered Vibration, all peaks are below 0.010 in/sec




Figure 57: Pump ODE-Z Filtered Vibration, the highest peak is 0.016 in/sec at 3,551 cpm (2X run speed)

The motor and pump vibration are very low at all locations.

TEST DISCUSSIONS

HYDRAULIC OPERATION

- Discharge valve could not be placed on piping, no results

ELECTRICAL OPERATION

- No electrical data collected

MECHANICAL OPERATION

- Pump vibration is well below the Hydraulic Institute Standards with the highest vibration being 0.052 in/sec rms
- This pump is running very well

FIELD INSPECTION

TEST RESULTS

The alignment between the pump and motor shaft was measured. The vertical offset misalignment is 0.0005" and the angular misalignment is 0.0069". The horizontal offset misalignment is 0.0002" and the angular misalignment is 0.0224". The alignment needs to be corrected.

OTHER OBSERVATIONS

The eccentric reducer on the suction side of the pump is located too close to the pump, see Figure 47. This reducer should be positioned farther from the pump to ensure no cavitation or hydraulic issues.

BOOSTER PUMP #3

HYDRAULIC PERFORMANCE TESTING

TEST RESULTS

The coupling on the discharge piping was to be used for the discharge gage. The discharge and suction valves were closed but the pressure could not be relieved. The plug in the coupling could not be pulled because the valves would not seal off the pressure.

Below are the vibration readings recorded on this pump:

UNFILTERED VIBRATION READINGS			
Location		Reading (in/sec rms)	Below HI Limits?
MOTOR	ODE-X	0.075	Yes
	ODE-Y	0.058	Yes
	ODE-Z	0.073	Yes
	DE-X	0.153	Yes
	DE-Y	0.089	Yes
PUMP	DE-X	0.025	Yes
	DE-Y	0.014	Yes
	ODE-X	0.022	Yes
	ODE-Y	0.017	Yes
	ODE-Z	0.028	Yes




Figure 58: Motor ODE-Y Filtered Vibration, the highest peak is 0.029 in/sec at 14,246 cpm (8X run speed) with other peaks at 1X, 2X, 3X, 4X, 5X, 6X, 7X, and 9X




Figure 59: Motor ODE-X Filtered Vibration, the highest peak is 0.035 in/sec at 5,340 cpm (3X run speed) with other peaks at 1X, 2X, 4X, 5X, 6X, 7X, 8X, and 9X




Figure 60: Motor ODE-Z Filtered Vibration, the highest peak is 0.032 in/sec at 14,242 cpm (8X run speed) with other peaks at 3X, 6X, 7X, 8X, 9X, 10X, 11X, and 12X




Figure 61: Motor DE-Y Filtered Vibration, highest peak is 0.022 in/sec at 8,816cpm (4.9X run speed) with other peaks at 1X, 3X, 4X, 6X, 7X, 8X, and 9X




Figure 62: Motor DE-X Filtered Vibration, highest peak is 0.101 in/sec at 5,340 cpm (3X run speed) with other peaks at 1X, 2X, 4X, 5X, 6X, 7X, 8X, 9X, 10X, 11X, and 12X




Figure 63: Pump DE-Y Filtered Vibration, all peaks are below 0.005 in/sec




Figure 64: Pump DE-X Filtered Vibration, all peaks are below 0.015 in/sec




Figure 65: Pump ODE-Y Filtered Vibration, all peaks are below 0.010 in/sec




Figure 66: Pump ODE-X Filtered Vibration, all peaks are below 0.010 in/sec




Figure 67: Pump ODE-Z Filtered Vibration, all peaks are below 0.005 in/sec

The motor vibration has peaks at 1X up to 12X consistently. This is an indication of looseness in the motor or bearings. The motor should be inspected soon.

The pump vibration is very low.

TEST DISCUSSIONS

HYDRAULIC OPERATION

- Discharge valve could not be placed on piping, no results

ELECTRICAL OPERATION

- No electrical data collected

MECHANICAL OPERATION

- Motor vibration is slightly above the HI limits with the highest vibration being 0.153 in/sec
- Pump vibration is well below the HI limits with the highest vibration being 0.028 in/sec rms
- This pump is still running very well

FIELD INSPECTION

TEST RESULTS

The alignment between the pump and motor shaft was measured. The vertical offset misalignment is 0.0001" and the angular misalignment is 0.0021". The horizontal offset misalignment is 0.0120" and the angular misalignment is 0.0473". The alignment needs to be corrected.

OTHER OBSERVATIONS

The eccentric reducer on the suction side of the pump is located too close to the pump, see Figure 47. This reducer should be positioned farther from the pump to ensure no cavitation or hydraulic issues.

BOOSTER PUMP #4

HYDRAULIC PERFORMANCE TESTING

TEST RESULTS

The coupling on the discharge piping was to be used for the discharge gage. The discharge and suction valves were closed but the pressure could not be relieved. The plug in the coupling could not be pulled because the valves would not seal off the pressure.

Below are the vibration readings recorded on this pump:

UNFILTERED VIBRATION READINGS			
Location		Reading (in/sec rms)	Below HI Limits?
MOTOR	ODE-X	0.069	Yes
	ODE-Y	0.196	No
	ODE-Z	0.179	No
	DE-X	0.142	Yes
	DE-Y	0.098	Yes
PUMP	DE-X	0.139	Yes
	DE-Y	0.037	Yes
	ODE-X	0.052	Yes
	ODE-Y	0.030	Yes
	ODE-Z	0.080	Yes




Figure 68: Motor ODE-Y Filtered Vibration, the highest peak is 0.155 in/sec at 3,548 cpm (2X run speed) with other peaks at 1X, 3X, 4X, 5X, 7X, and 8X




Figure 69: Motor ODE-X Filtered Vibration, the highest peak is 0.039 in/sec at 3,548 cpm (2X run speed) with other peaks at 3X, 4X, 6X, and 7X




Figure 70: Motor ODE-Z Filtered Vibration, the highest peak is 0.157 in/sec at 3,548 cpm (2X run speed) with other peak at 1X




Figure 71: Motor DE-Y Filtered Vibration, highest peak is 0.075 in/sec at 7,200 cpm (4X run speed) with other peaks at 1X, 2X, 3X, 5X, 7X, and 8X




Figure 72: Motor DE-X Filtered Vibration, highest peak is 0.118 in/sec at 3,548 cpm (2X run speed) with other peaks at 1X, 3X, 4X, 5X, and 7X




Figure 73: Pump DE-Y Filtered Vibration, all peaks are below 0.015 in/sec




Figure 74: Pump DE-X Filtered Vibration, all peaks are below 0.015 in/sec




Figure 75: Pump ODE-Y Filtered Vibration, all peaks are below 0.010 in/sec




Figure 76: Pump ODE-X Filtered Vibration, all peaks are below 0.015 in/sec




Figure 77: Pump ODE-Z Filtered Vibration, the highest peak is 0.063 in/sec at 3,548 cpm (2X run speed)

The motor vibration has peaks at 1X up to 7X consistently. This is an indication of looseness in the motor or bearings. The motor should be inspected soon.

The pump vibration is low and has a consistent vibration at 2X which is likely caused parallel and angular misalignment.

TEST DISCUSSIONS

HYDRAULIC OPERATION

- Discharge valve could not be placed on piping, no results

ELECTRICAL OPERATION

- No electrical data collected

MECHANICAL OPERATION

- Motor vibration is above the HI limits with the highest vibration being 0.196 in/sec
- Pump vibration is just below the HI limits with the highest vibration being 0.139 in/sec rms
- This pump is still running well but should be monitored for any increase in vibration

FIELD INSPECTION

TEST RESULTS

The alignment between the pump and motor shaft was measured. The vertical offset misalignment is 0.0077" and the angular misalignment is 0.0638". The horizontal offset misalignment is 0.0037" and the angular misalignment is 0.0353". The alignment needs to be corrected.

OTHER OBSERVATIONS


The eccentric reducer on the suction side of the pump is located too close to the pump, see Figure 47. This reducer should be positioned farther from the pump to ensure no cavitation or hydraulic issues.

REFERENCE DOCUMENTS

<u>ITEM</u>	<u>DATE</u>	<u>DOCUMENT DESCRIPTION</u>
APPENDIX A	6/2/2015	Old Booster PS, BP-1 Field Test Data
	6/2/2015	Old Booster PS, BP-2 Field Test Data
	6/1/2015	Old Booster PS, BP-3 Field Test Data
	6/1/2015	Old Booster PS, BP-4 Field Test Data
	6/2/2015	New Booster PS, BP-1 Field Test Data
	6/2/2015	New Booster PS, BP-2 Field Test Data
	6/3/2015	New Booster PS, BP-3 Field Test Data
	6/2/2015	New Booster PS, BP-4 Field Test Data
APPENDIX B	6/3/2015	New Booster PS, BP-1 Alignment Data
	6/3/2015	New Booster PS, BP-2 Alignment Data
	6/3/2015	New Booster PS, BP-3 Alignment Data
	6/3/2015	New Booster PS, BP-4 Alignment Data
APPENDIX C	N/A	Pump Catalog Curves
APPENDIX D	Various	Calibration Certificates

APPENDIX A

FIELD TESTING DATA



SMITH PUMP COMPANY, INC.

OLD BOOSTER PUMP STATION, BP-1

NAMEPLATE DATA

MOTOR:	USEM	PUMP:	LAYNE 12WMC
SERIAL NO.:	1216576	SERIAL NO.:	41376
RATED HP:	40 hp	RATED FLOW:	1,000 gpm
RATED SPEED:	1,785 rpm	RATED HEAD:	102' TDH
FLA:	49 A	RATED SPEED:	

BY: SHANE WALLACE
DATE: 6/2/2015
PROJECT #: 172202
ENGINEER: FREESE & NICHOLS, INC.
CONTRACTOR: N/A
STATION: OLD PUMP STATION

SUC. GAGE TO CL OF DISCH. (FT): 1.4
PIPE I.D. AT SUC. GAGE (IN): N/A
DISCH. GAGE TO CL OF DISCH. (FT) 1.6
PIPE I.D. AT DISCH. GAGE (IN): 8.6
MOTOR EFFICIENCY (%): 92.4%


			CALCULATIONS			
			CORRECTED VALUES			
			GIVEN VALUES			
START: 10:10 AM						
TIME:	10:15 AM	10:30 AM				
RUN TIME (MIN):	5	20				
TARGE SPEED (RPM):	1,785	1,785	1,785	1,785	1,785	
FLOW METER (GPM):	1,136	1,115				
SUCTION PRESSURE (PSI):	8.5	8.3				
SUC. VELOCITY HEAD (FT):	0	0				
DISCH. PRESSURE (FT):	92	95				
DISCH. VELOCITY HEAD (FT):	0.61	0.59				
HEAD LOSS (FT) ¹ :	0.00	0.00				
TDH (FT):	73	77				
SPEED (RPM):	1,788	1,787				
L1-L2 VOLTAGE (V):	484	480				
L2-L3 VOLTAGE (V):	488	484				
L3-L1 VOLTAGE (V):	482	479				
L1 CURRENT (AMPS):	31	31				
L2 CURRENT (AMPS):	34	34				
L3 CURRENT (AMPS):	31	31				
POWER FACTOR:	0.75	0.75				
INPUT POWER (HP):	30	30				
SHAFT POWER (HP):	28	28				
BOWL POWER (HP):	21	22				
CORRECTED FLOW (GPM):	1,134	1,114				
CORRECTED TDH (FT):	73	76				
CORRECTED INPUT PWR (HP):	28	28				
CORRECTED BOWL PWR (HP):	21	21				
PUMP EFFICIENCY (%)	74.9	76.9				
TEMPERATURE (°C)						
HOTTEST STATOR (RTD 1-9)						
UPPER BRG. (RTD 10)						
LOWER BRG. (RTD 11)						
VIBRATION (IN/SEC RMS)						
MT-0	0.918	0.885				
MT-90	0.359	0.357				
MT-VERTICAL	0.085	0.083				
MB-0	0.707	0.684				
MB-90	0.221	0.238				
OTHER:						


NOTES:

- 1 - PIPE PLANS NOT AVAILABLE FOR SUCTION SIDE OF PUMP, HEAD LOSS ESTIMATED
- 2 -
- 3 -

CITY OF HUNTSVILLE, OLD BOOSTER PUMP STATION

Booster Pump #1 Field Performance Test





SMITH PUMP COMPANY, INC.

OLD BOOSTER PUMP STATION, BP-2

NAMEPLATE DATA

MOTOR:	USEM	PUMP:	LAYNE 12WMC
SERIAL NO.:	1216577	SERIAL NO.:	41377
RATED HP:	40 hp	RATED FLOW:	1,000 gpm
RATED SPEED:	1,785 rpm	RATED HEAD:	102' TDH
FLA:	49 A	RATED SPEED:	

BY: SHANE WALLACE
DATE: 6/2/2015
PROJECT #: 172202
ENGINEER: FREESE & NICHOLS, INC.
CONTRACTOR: N/A
STATION: OLD PUMP STATION


SUC. GAGE TO CL OF DISCH. (FT): 1.4
PIPE I.D. AT SUC. GAGE (IN): N/A
DISCH. GAGE TO CL OF DISCH. (FT) 1.6
PIPE I.D. AT DISCH. GAGE (IN): 14.7
MOTOR EFFICIENCY (%): 92.4%


		<table><tr><td>CALCULATIONS</td></tr><tr><td>CORRECTED VALUES</td></tr><tr><td>GIVEN VALUES</td></tr></table>					CALCULATIONS	CORRECTED VALUES	GIVEN VALUES
CALCULATIONS									
CORRECTED VALUES									
GIVEN VALUES									
		START: 9:15							
TIME:	9:18 AM	9:34 AM							
RUN TIME (MIN):									
TARGE SPEED (RPM):	1,785	1,785	1,785	1,785	1,785				
FLOW METER (GPM):	1,131	1,137							
SUCTION PRESSURE (PSI):	8.4	8.4							
SUC. VELOCITY HEAD (FT):	0	0							
DISCH. PRESSURE (FT):	95	95							
DISCH. VELOCITY HEAD (FT):	0.07	0.07							
HEAD LOSS (FT):	0.00	0.00							
TDH (FT):	76	76							
SPEED (RPM):	1,782	1,787							
L1-L2 VOLTAGE (V):	486	486							
L2-L3 VOLTAGE (V):	489	490							
L3-L1 VOLTAGE (V):	485	485							
L1 CURRENT (AMPS):	30	30							
L2 CURRENT (AMPS):	33	33							
L3 CURRENT (AMPS):	30	30							
POWER FACTOR:	0.74	0.74							
INPUT POWER (HP):	30	29							
SHAFT POWER (HP):	27	27							
BOWL POWER (HP):	22	22							
CORRECTED FLOW (GPM):	1,133	1,136							
CORRECTED TDH (FT):	76	76							
CORRECTED INPUT PWR (HP):	27	27							
CORRECTED BOWL PWR (HP):	22	22							
PUMP EFFICIENCY (%)	79.6	80.5							
TEMPERATURE (°C)									
HOTTEST STATOR (RTD 1-9)									
UPPER BRG. (RTD 10)									
LOWER BRG. (RTD 11)									
VIBRATION (IN/SEC RMS)									
MT-0	0.281	0.297							
MT-90	0.070	0.068							
MT-VERTICAL	0.043	0.043							
MB-0	0.224	0.225							
MB-90	0.046	0.047							
OTHER:									

NOTES:

- 1 -
- 2 -
- 3 -

CITY OF HUNTSVILLE, OLD PUMP STATION Booster Pump #2 Field Performance Test





SMITH PUMP COMPANY, INC.

OLD BOOSTER PUMP STATION, BP-3

NAMEPLATE DATA

MOTOR:	USEM	PUMP:	LAYNE 12THC
SERIAL NO.:	T06-391397-0001-GT-01	SERIAL NO.:	41378
RATED HP:	75 hp	RATED FLOW:	2,000 gpm
RATED SPEED:	1,785 rpm	RATED HEAD:	108' TDH
FLA:	90.7 A	RATED SPEED:	

BY: SHANE WALLACE
DATE: 6/1/2015
PROJECT #: 172202
ENGINEER: FREESE & NICHOLS, INC.
CONTRACTOR: N/A
STATION: OLD PUMP STATION


SUC. GAGE TO CL OF DISCH. (FT): 1.4
PIPE I.D. AT SUC. GAGE (IN): N/A
DISCH. GAGE TO CL OF DISCH. (FT) 1.6
PIPE I.D. AT DISCH. GAGE (IN): 14.7
MOTOR EFFICIENCY (%): 92.4%


			CALCULATIONS
			CORRECTED VALUES
			GIVEN VALUES
START: 2:10 PM			
TIME:	2:20 PM	2:35 PM	
RUN TIME (MIN):	10	25	
TARGE SPEED (RPM):	1,785	1,785	
FLOW METER (GPM):	2,340	2,260	
SUCTION PRESSURE (PSI):	9.3	9.7	
SUC. VELOCITY HEAD (FT):	0	0	
DISCH. PRESSURE (FT):	96	97	
DISCH. VELOCITY HEAD (FT):	0.30	0.28	
HEAD LOSS (FT):	0.00	0.00	
TDH (FT):	75	75	
SPEED (RPM):	1,790	1,791	
L1-L2 VOLTAGE (V):	478	481	
L2-L3 VOLTAGE (V):	476	486	
L3-L1 VOLTAGE (V):	482	480	
L1 CURRENT (AMPS):	72	72	
L2 CURRENT (AMPS):	81	81	
L3 CURRENT (AMPS):	74	75	
POWER FACTOR:	0.67	0.67	
INPUT POWER (HP):	64	64	
SHAFT POWER (HP):	59	59	
BOWL POWER (HP):	44	43	
CORRECTED FLOW (GPM):	2,333	2,252	
CORRECTED TDH (FT):	75	75	
CORRECTED INPUT PWR (HP):	58	58	
CORRECTED BOWL PWR (HP):	44	42	
PUMP EFFICIENCY (%)	75.4	72.9	
TEMPERATURE (°C)			
HOTTEST STATOR (RTD 1-9)			
UPPER BRG. (RTD 10)			
LOWER BRG. (RTD 11)			
VIBRATION (IN/SEC RMS)			
MT-0	0.181	0.189	
MT-90	0.061	0.080	
MT-VERTICAL	0.048	0.037	
MB-0	0.084	0.129	
MB-90	0.034	0.036	
OTHER:			

NOTES:

- 1 -
- 2 -
- 3 -

CITY OF HUNTSVILLE, OLD PUMP STATION Booster Pump #3 Field Performance Test





SMITH PUMP COMPANY, INC.

OLD BOOSTER PUMP STATION, BP-4

NAMEPLATE DATA

MOTOR:	USEM	PUMP:	LAYNE 12THC
SERIAL NO.:	1216527	SERIAL NO.:	41379
RATED HP:	75 hp	RATED FLOW:	2,000 gpm
RATED SPEED:	1,785 rpm	RATED HEAD:	108' TDH
FLA:	90.7 A	RATED SPEED:	

BY: SHANE WALLACE
DATE: 6/1/2015
PROJECT #: 172202
ENGINEER: FREESE & NICHOLS, INC.
CONTRACTOR: N/A
STATION: OLD PUMP STATION

SUC. GAGE TO CL OF DISCH. (FT): 1.4
PIPE I.D. AT SUC. GAGE (IN): N/A
DISCH. GAGE TO CL OF DISCH. (FT) 1.6
PIPE I.D. AT DISCH. GAGE (IN): 14.7
MOTOR EFFICIENCY (%): 92.4%


START: 10:45 AM


	CALCULATIONS	
	CORRECTED VALUES	
	GIVEN VALUES	
TIME:	11:10 AM	11:55 AM
RUN TIME (MIN):	25	70
TARGE SPEED (RPM):	1,785	1,785
FLOW METER (GPM):	2,400	2,445
SUCTION PRESSURE (PSI):	10.0	9.8
SUC. VELOCITY HEAD (FT):	0	0
DISCH. PRESSURE (FT):	94	94
DISCH. VELOCITY HEAD (FT):	0.32	0.33
HEAD LOSS (FT):	0.00	0.00
TDH (FT):	71	72
SPEED (RPM):	1,785	1,788
L1-L2 VOLTAGE (V):	486	486
L2-L3 VOLTAGE (V):	482	480
L3-L1 VOLTAGE (V):	480	481
L1 CURRENT (AMPS):	62	62
L2 CURRENT (AMPS):	67	68
L3 CURRENT (AMPS):	62	61
POWER FACTOR:	0.87	0.87
INPUT POWER (HP):	64	64
SHAFT POWER (HP):	59	59
BOWL POWER (HP):	43	44
CORRECTED FLOW (GPM):	2,400	2,441
CORRECTED TDH (FT):	71	72
CORRECTED INPUT PWR (HP):	59	58
CORRECTED BOWL PWR (HP):	43	44
PUMP EFFICIENCY (%)	73.6	75.5
TEMPERATURE (°C)		
HOTTEST STATOR (RTD 1-9)		
UPPER BRG. (RTD 10)		
LOWER BRG. (RTD 11)		
VIBRATION (IN/SEC RMS)		
MT-0	0.371	0.383
MT-90	0.328	0.298
MT-VERTICAL	0.103	0.099
MB-0	0.246	0.255
MB-90	0.184	0.171
OTHER:		

NOTES:

- 1 -
- 2 -
- 3 -

CITY OF HUNTSVILLE, OLD PUMP STATION Booster Pump #4 Field Performance Test





SMITH PUMP COMPANY, INC.

NEW BOOSTER PUMP STATION, BP-1

NAMEPLATE DATA

MOTOR:	SIEMENS	PUMP:	GOULDS 3405, 6x8x12
SERIAL NO.:	51-380-561 LR68761-1	SERIAL NO.:	250B662
RATED HP:	50	RATED FLOW:	1,400
RATED SPEED:	1,770	RATED HEAD:	110
FLA:	58.5	RATED SPEED:	1,800


BY: SHANE WALLACE
DATE: 6/2/2015
PROJECT #: 172202
ENGINEER: FREESE & NICHOLS, INC.
CONTRACTOR: N/A
STATION: NEW PUMP STATION

SUC. GAGE TO CL OF DISCH. (FT): 0.0
PIPE I.D. AT SUC. GAGE (IN): 12.6
DISCH. GAGE TO CL OF DISCH. (FT) 1.7
PIPE I.D. AT DISCH. GAGE (IN): 10.6
MOTOR EFFICIENCY (%): 93.0% (1)

		START: 1:45 PM						CALCULATIONS		
								CORRECTED VALUES		
								GIVEN VALUES		
TIME:		2:00 PM	2:22 PM							
RUN TIME (MIN):		15	37							
TARGE SPEED (RPM):		1,750	1,750	1,750	1,750	1,750	1,750			
FLOW METER (GPM):		1,800	1,840							
SUCTION PRESSURE (PSI):		9.9	10.1							
SUC. VELOCITY HEAD (FT):		0.33	0.34							
DISCH. PRESSURE (FT):		92	91							
DISCH. VELOCITY HEAD (FT):		0.67	0.70							
HEAD LOSS (FT):		0.00	0.00							
TDH (FT):		71	70							
SPEED (RPM):		1,767	1,767							
L1-L2 VOLTAGE (V):		481	481							
L2-L3 VOLTAGE (V):		478	474							
L3-L1 VOLTAGE (V):		475	488							
L1 CURRENT (AMPS):		65	66							
L2 CURRENT (AMPS):		65	65							
L3 CURRENT (AMPS):		61	61							
POWER FACTOR:		0.89	0.87							
INPUT POWER (HP):		56	56							
SHAFT POWER (HP):		52	52							
BOWL POWER (HP):		32	32							
CORRECTED FLOW (GPM):		1,783	1,822							
CORRECTED TDH (FT):		70	68							
CORRECTED INPUT PWR (HP):		51	51							
CORRECTED BOWL PWR (HP):		31	31							
PUMP EFFICIENCY (%):		62.1	62.2							
TEMPERATURE (°C)										
HOTTEST STATOR (RTD 1-9)										
UPPER BRG. (RTD 10)										
LOWER BRG. (RTD 11)										
MOTOR	VIBRATION (IN/SEC RMS)									
	ODE-X	0.044	0.037							
	ODE-Y	0.055	0.066							
	ODE-Z	0.067	0.057							
	DE-X	0.076	0.072							
	DE-Y	0.043	0.041							
PUMP	DE-X	0.034	0.038							
	DE-Y	0.026	0.028							
	ODE-X	0.021	0.020							
	ODE-Y	0.014	0.014							
	ODE-Z	0.031	0.030							
OTHER:										

CITY OF HUNTSVILLE, NEW BOOSTER PUMP STATION

Booster Pump #1 Field Performance Test





SMITH PUMP COMPANY, INC.

NEW BOOSTER PUMP STATION, BP-2

NAMEPLATE DATA

MOTOR:	SIEMENS	PUMP:	GOULDS 3405, 6x8x12
SERIAL NO.:	F07TESP.36 1	SERIAL NO.:	250B662-1
RATED HP:	50	RATED FLOW:	1,400
RATED SPEED:	1,770	RATED HEAD:	110
FLA:	58	RATED SPEED:	1,800

BY: SHANE WALLACE
DATE: 6/2/2015
PROJECT #: 172202
ENGINEER: FREESE & NICHOLS, INC.
CONTRACTOR: N/A
STATION: NEW PUMP STATION

SUC. GAGE TO CL OF DISCH. (FT): 0.0
PIPE I.D. AT SUC. GAGE (IN): N/A
DISCH. GAGE TO CL OF DISCH. (FT) N/A (1)
PIPE I.D. AT DISCH. GAGE (IN): N/A (1)
MOTOR EFFICIENCY (%): 93.0%


START:

CALCULATIONS
CORRECTED VALUES
GIVEN VALUES

TIME:	
RUN TIME (MIN):	
TARGE SPEED (RPM):	1,750 1,750 1,750 1,750 1,750 1,750
FLOW METER (GPM):	
SUCTION PRESSURE (PSI):	
SUC. VELOCITY HEAD (FT):	
DISCH. PRESSURE (FT):	
DISCH. VELOCITY HEAD (FT):	
HEAD LOSS (FT):	
TDH (FT):	
SPEED (RPM):	
L1-L2 VOLTAGE (V):	
L2-L3 VOLTAGE (V):	
L3-L1 VOLTAGE (V):	
L1 CURRENT (AMPS):	
L2 CURRENT (AMPS):	
L3 CURRENT (AMPS):	
POWER FACTOR:	
INPUT POWER (HP):	
SHAFT POWER (HP):	
BOWL POWER (HP):	
CORRECTED FLOW (GPM):	
CORRECTED TDH (FT):	
CORRECTED INPUT PWR (HP):	
CORRECTED BOWL PWR (HP):	
PUMP EFFICIENCY (%)	
TEMPERATURE (°C)	
HOTTEST STATOR (RTD 1-9)	
UPPER BRG. (RTD 10)	
LOWER BRG. (RTD 11)	
VIBRATION (IN/SEC RMS)	
ODE-X	0.025
ODE-Y	0.025
ODE-Z	0.022
DE-X	0.052
DE-Y	0.050
DE-Z	0.029
ODE-X	0.019
ODE-Y	0.021
ODE-Z	0.020
ODE-X	0.027
OTHER:	

NOTES:

- 1 - DISCHARGE PIPING COULD NOT BE ISOLATED FROM DISCHARGE PRESSURE, THEREFORE NO GAGE COULD BE PLACED
- 2 -
- 3 -



SMITH PUMP COMPANY, INC.

NEW BOOSTER PUMP STATION, BP-3

NAMEPLATE DATA

MOTOR:	POWER TECH	PUMP:	GOULDS 3405, 6x8x12
SERIAL NO.:	SH10080001	SERIAL NO.:	2508662-4
RATED HP:	50	RATED FLOW:	1,400
RATED SPEED:	1,775	RATED HEAD:	110
FLA:	59.7	RATED SPEED:	1,800

BY: SHANE WALLACE
DATE: 6/3/2015
PROJECT #: 172202
ENGINEER: FREESE & NICHOLS, INC.
CONTRACTOR: N/A
STATION: NEW PUMP STATION

SUC. GAGE TO CL OF DISCH. (FT): 0.0
PIPE I.D. AT SUC. GAGE (IN): N/A
DISCH. GAGE TO CL OF DISCH. (FT) N/A (1)
PIPE I.D. AT DISCH. GAGE (IN): N/A (1)
MOTOR EFFICIENCY (%): 91.7%


START:

CALCULATIONS
CORRECTED VALUES
GIVEN VALUES

TIME:	
RUN TIME (MIN):	
TARGE SPEED (RPM):	1,750 1,750 1,750 1,750 1,750 1,750
FLOW METER (GPM):	
SUCTION PRESSURE (PSI):	
SUC. VELOCITY HEAD (FT):	
DISCH. PRESSURE (FT):	
DISCH. VELOCITY HEAD (FT):	
HEAD LOSS (FT):	
TDH (FT):	
SPEED (RPM):	
L1-L2 VOLTAGE (V):	
L2-L3 VOLTAGE (V):	
L3-L1 VOLTAGE (V):	
L1 CURRENT (AMPS):	
L2 CURRENT (AMPS):	
L3 CURRENT (AMPS):	
POWER FACTOR:	
INPUT POWER (HP):	
SHAFT POWER (HP):	
BOWL POWER (HP):	
CORRECTED FLOW (GPM):	
CORRECTED TDH (FT):	
CORRECTED INPUT PWR (HP):	
CORRECTED BOWL PWR (HP):	
PUMP EFFICIENCY (%)	
TEMPERATURE (°C)	
HOTTEST STATOR (RTD 1-9)	
UPPER BRG. (RTD 10)	
LOWER BRG. (RTD 11)	
VIBRATION (IN/SEC RMS)	
ODE-X	0.075
ODE-Y	0.058
ODE-Z	0.073
DE-X	0.153
DE-Y	0.089
DE-Z	0.025
ODE-X	0.014
ODE-Y	0.022
ODE-Z	0.017
ODE-X	0.028
OTHER:	

NOTES:

- 1 - DISCHARGE PIPING COULD NOT BE ISOLATED FROM DISCHARGE PRESSURE, THEREFORE NO GAGE COULD BE PLACED
- 2 -
- 3 -



SMITH PUMP COMPANY, INC.

NEW BOOSTER PUMP STATION, BP-4

NAMEPLATE DATA

MOTOR:	SIEMENS	PUMP:	GOULDS 3405, 6x8x12
SERIAL NO.:	51-380-861 LR68761-1	SERIAL NO.:	250B662-2
RATED HP:	50	RATED FLOW:	1,400
RATED SPEED:	1,770	RATED HEAD:	110
FLA:	58.5	RATED SPEED:	1,800

BY: SHANE WALLACE
DATE: 6/2/2015
PROJECT #: 172202
ENGINEER: FREESE & NICHOLS, INC.
CONTRACTOR: N/A
STATION: NEW PUMP STATION

SUC. GAGE TO CL OF DISCH. (FT): 0.0
PIPE I.D. AT SUC. GAGE (IN): N/A
DISCH. GAGE TO CL OF DISCH. (FT) N/A (1)
PIPE I.D. AT DISCH. GAGE (IN): N/A (1)
MOTOR EFFICIENCY (%): 93.0% (2)

START:

CALCULATIONS
CORRECTED VALUES
GIVEN VALUES

TIME:	
RUN TIME (MIN):	
TARGE SPEED (RPM):	1,750
FLOW METER (GPM):	
SUCTION PRESSURE (PSI):	
SUC. VELOCITY HEAD (FT):	
DISCH. PRESSURE (FT):	
DISCH. VELOCITY HEAD (FT):	
HEAD LOSS (FT):	
TDH (FT):	
SPEED (RPM):	
L1-L2 VOLTAGE (V):	
L2-L3 VOLTAGE (V):	
L3-L1 VOLTAGE (V):	
L1 CURRENT (AMPS):	
L2 CURRENT (AMPS):	
L3 CURRENT (AMPS):	
POWER FACTOR:	
INPUT POWER (HP):	
SHAFT POWER (HP):	
BOWL POWER (HP):	
CORRECTED FLOW (GPM):	
CORRECTED TDH (FT):	
CORRECTED INPUT PWR (HP):	
CORRECTED BOWL PWR (HP):	
PUMP EFFICIENCY (%)	
TEMPERATURE (°C)	
HOTTEST STATOR (RTD 1-9)	
UPPER BRG. (RTD 10)	
LOWER BRG. (RTD 11)	
VIBRATION (IN/SEC RMS)	
ODE-X	0.069
ODE-Y	0.196
ODE-Z	0.179
DE-X	0.142
DE-Y	0.098
DE-Z	0.139
ODE-X	0.037
ODE-Y	0.052
ODE-Z	0.030
ODE-X	0.080
OTHER:	

NOTES:

- 1 - DISCHARGE PIPING COULD NOT BE ISOLATED FROM DISCHARGE PRESSURE, THEREFORE NO GAGE COULD BE PLACED
- 2 - MOTOR EFFICIENCY COULD NOT BE FOUND ON NAME TAG, EFFICIENCY IS ASSUMED
- 3 -

APPENDIX B

ALIGNMENT DATA

Smith Pump Co., Inc.

Department: Pump Shop

Mr. Larry Hernandez


File information

Name: Position-54
Company: Freeze & Nichols
Plant: 172202
Area: Huntsville
Machine train: BP-1
Comment:
Username:
Note 1:
Note 2:
Note 3:
Note 4:
Note 5:
Note 6:
Note 7:
Measured: 6/3/1999 8:33:00 AM

Description

Component:	Type:	Mounting:
Machine A:	Standard	Static machine
Coupling 1:	Short flex	
Machine B:	Standard	4 Feet

Dimensions (graphical)




Dimensions**Coupling 1:**

Coupling diameter	10.000 [inch]
Distance to the right machine	9.000 [inch]
RPM	1770 [RPM]

Machine A:**Machine B:**

Length	12.000 [inch]
--------	---------------

Result Graphic**Corrections**

	vertical	horizontal Units
Machine A:		
Stationary Machine		
Machine B:		
Foot 1	9.6	143.9 [mils]
Foot 2	32.7	289.4 [mils]

Coupling Results

	vertical	horizontal Units
Coupling 1:		
Actual minus specification		
Gap	19.3	121.2 [mils]
Offset	7.8	-34.8 [mils]
Actual		

Gap	19.3	121.2 [mils]
Offset	2.8	-34.8 [mils]

Measurements

Type	vertical	horizontal	SD Date / Time
<i>Coupling 1:</i>			
# Sweep			--- 6/3/1999 8:33:...
Distance laser - prism: 6.000 [inch]			
Distance laser - coupling reference: 3.000 [inch]			
Gap	19.3 mils	121.2 mils	
Offset	2.8 mils	-34.8 mils	

Thermal growth

	vertical	horizontal Units
<i>Machine A:</i>		
<i>No thermal growth defined!</i>		
<i>Machine B:</i>		
Left foot	5.0	0.0 [mils]
Right foot	5.0	0.0 [mils]

Smith Pump Co., Inc.

Department: Pump Shop

Mr. Larry Hernandez


File information

Name: Position-55
Company: Freeze & Nichols
Plant: 172202
Area: Huntsville
Machine train: BP-2
Comment:
Username:
Note 1:
Note 2:
Note 3:
Note 4:
Note 5:
Note 6:
Note 7:
Measured: 6/3/1999 8:54:00 AM

Description

Component:	Type:	Mounting:
Machine A:	Standard	Static machine
Coupling 1:	Short flex	
Machine B:	Standard	4 Feet

Dimensions (graphical)




Dimensions*Coupling 1:*

Coupling diameter	10.000 [inch]
Distance to the right machine	9.250 [inch]
RPM	1770 [RPM]

*Machine A:**Machine B:*

Length	12.000 [inch]
--------	---------------

Result Graphic**Corrections**


	vertical	horizontal Units
<i>Machine A:</i>		
<i>Stationary Machine</i>		
<i>Machine B:</i>		
Foot 1	-5.8	20.9 [mils]
Foot 2	-14.1	47.9 [mils]

Coupling Results

	vertical	horizontal Units
<i>Coupling 1:</i>		
<i>Actual minus specification</i>		
Gap	-6.9	22.4 [mils]
Offset	-0.5	-0.2 [mils]
<i>Actual</i>		

Gap	-6.9	22.4 [mils]
Offset	-0.5	-0.2 [mils]

Measurements

Type	vertical	horizontal	SD Date / Time
Coupling 1:			
#		Sweep	--- 6/3/1999 8:54:...
Distance laser - prism: 5.500 [inch]			
Distance laser - coupling reference: 2.750 [inch]			
Gap	-6.9 mils	22.4 mils	
Offset	-0.5 mils	-0.2 mils	

Smith Pump Co., Inc.

Department: Pump Shop

Mr. Larry Hernandez


File information

Name: Position-56
 Company: Freeze & Nichols
 Plant: 172202
 Area: Huntsville
 Machine train: BP3
 Comment:
 Username:
 Note 1:
 Note 2:
 Note 3:
 Note 4:
 Note 5:
 Note 6:
 Note 7:
 Measured: 6/3/1999 9:09:00 AM

Description

Component:	Type:	Mounting:
Machine A:	Standard	Static machine
Coupling 1:	Short flex	
Machine B:	Standard	4 Feet

Dimensions (graphical)




Dimensions*Coupling 1:*

Coupling diameter	10.000 [inch]
Distance to the right machine	9.000 [inch]
RPM	1775 [RPM]

*Machine A:**Machine B:*

Length	12.000 [inch]
--------	---------------

Result Graphic**Corrections**


	vertical	horizontal Units
<i>Machine A:</i>		
<i>Stationary Machine</i>		
<i>Machine B:</i>		
Foot 1	2.0	-30.6 [mils]
Foot 2	4.6	-87.4 [mils]

Coupling Results

	vertical	horizontal Units
<i>Coupling 1:</i>		
<i>Actual minus specification</i>		
Gap	2.1	-47.3 [mils]
Offset	-0.1	-12.0 [mils]
<i>Actual</i>		

Gap	2.1	-47.3 [mils]
Offset	-0.1	-12.0 [mils]

Measurements

Type	vertical	horizontal	SD Date / Time
Coupling 1:			
#		Sweep	--- 6/3/1999 9:09:...
Distance laser - prism: 6.000 [inch]			
Distance laser - coupling reference: 3.000 [inch]			
Gap	2.1 mils	-47.3 mils	
Offset	-0.1 mils	-12.0 mils	

Smith Pump Co., Inc.

Department: Pump Shop


Mr. Larry Hernandez

File information

Name: Position-57
 Company: Freeze & Nichols
 Plant: 172202
 Area: Huntsville
 Machine train: BP-4
 Comment:
 Username:
 Note 1:
 Note 2:
 Note 3:
 Note 4:
 Note 5:
 Note 6:
 Note 7:
 Measured: 6/3/1999 9:19:00 AM

Description

Component:	Type:	Mounting:
Machine A:	Standard	Static machine
Coupling 1:	Short flex	
Machine B:	Standard	4 Feet


Dimensions (graphical)

Dimensions**Coupling 1:**

Coupling diameter	10.000 [inch]
Distance to the right machine	9.500 [inch]
RPM	1770 [RPM]

Machine A:**Machine B:**

Length	12.000 [inch]
--------	---------------

Result Graphic**Corrections**


	vertical	horizontal Units
Machine A:		
Stationary Machine		
Machine B:		
Foot 1	-68.3	37.2 [mils]
Foot 2	-144.9	79.5 [mils]

Coupling Results

	vertical	horizontal Units
Coupling 1:		
Actual minus specification		
Gap	-63.8	35.3 [mils]
Offset	7.7	-3.7 [mils]
Actual		

Gap	-63.8	35.3 [mils]
Offset	7.7	-3.7 [mils]

Measurements

Type	vertical	horizontal	SD Date / Time
Coupling 1:			
#		Sweep	--- 6/3/1999 9:19:...
Distance laser - prism: 5.000 [inch]			
Distance laser - coupling reference: 2.500 [inch]			
Gap	-63.8 mils	35.3 mils	
Offset	7.7 mils	-3.7 mils	

APPENDIX C

PUMP CATALOG CURVES

THESE CURVES SHOW THE GENERAL SHAPE OF THE PUMP BOWL CHARACTERISTICS UNDER SHOP TESTS AT THE CONSTANT SPEED INDICATED. A TOLERANCE OF PLUS OR MINUS 2% MUST BE ALLOWED IN THE GUARANTEED CAPACITY, HEAD, AND EFFICIENCY AT THE RATED POINT WHEN PUMPING NON-GASEOUS WATER, FREE FROM DETRITUS, AT A TEMPERATURE NOT OVER 86° FAHR., AND WITH THE LOWEST IMPELLER SUBMERGED.

FOR

ADDRESS

TYPE OF PUMP FIG. **12WMC**


R.P.M. **1750**

SIZE OF PUMP **12 INS 2 STAGES 6W15** IMPELLER

FIELD PERFORMANCE

THE FIELD PERFORMANCE AS SHOWN BELOW, MAKES ALLOWANCE FOR ALL THE HYDRAULIC AND MECHANICAL LOSSES IN THE COLUMN AND SHAFT OF THE INSTALLATION ACCORDING TO THE STANDARDS OF THE HYDRAULIC INSTITUTE. THE FIELD PUMPING HEAD IS THE LIFT FROM THE WELL PLUS THE DISCHARGE HEAD MEASURED AT THE DISCHARGE CONNECTION AT THE SURFACE.

COLUMN	INS.	LENGTH	FT.	SHAFT DIA.
CAPACITY		U. S. GPM	FIELD	PUMPING HEAD
FIELD B.H.P.				FIELD EFFICIENCY
MOTOR EFF.				WIRE TO WATER EFFICIENCY
NOTES				



THESE CURVES SHOW THE GENERAL SHAPE OF THE PUMP BOWL CHARACTERISTICS UNDER SHOP TESTS AT THE CONSTANT SPEED INDICATED. A TOLERANCE OF PLUS OR MINUS 2% MUST BE ALLOWED IN THE GUARANTEED CAPACITY, HEAD, AND EFFICIENCY AT THE RATED POINT WHEN PUMPING NON-GASEOUS WATER, FREE FROM DETRITUS, AT A TEMPERATURE NOT OVER 85° FAHR., AND WITH THE LOWEST IMPELLER SUBMERGED.

FOR

ADDRESS

TYPE OF PUMP MD

12 THC

R.P.M. 1770

SIZE OF PUMP

12 INS 2 STAGES 6T11A IMPELLER

FIELD PERFORMANCE

THE FIELD PERFORMANCE AS SHOWN BELOW, MAKES ALLOWANCE FOR ALL THE HYDRAULIC AND MECHANICAL LOSSES IN THE COLUMN AND SHAFT OF THE INSTALLATION ACCORDING TO THE STANDARDS OF THE HYDRAULIC INSTITUTE. THE FIELD PUMPING HEAD IS THE LIFT FROM THE WELL PLUS THE DISCHARGE HEAD MEASURED AT THE DISCHARGE CONNECTION AT THE SURFACE.

COLUMN	INS	LENGTH	FT	SHAFT DIA.
CAPACITY		U. S. GPM	FIELD	PUMPING HEAD
FIELD B.H.P.				FIELD EFFICIENCY
MOTOR EFF.				WIRE TO WATER EFFICIENCY
NOTES				

TOTAL HEAD IN FEET
150
140
130
120
110
100
90
80
70
60
50
40

PERCENT EFFICIENCY


80
70
60
50
40
30
20
10
0


EFFICIENCY %

BHP SP. GR. = 1.0

U. S. GALLONS PER MINUTE

BHP
60
40
20
0






**1750
R.P.M.**

APPENDIX D

CALIBRATION CERTIFICATES



Equip. No. 1723
MPC CALIBRATION INC.
670 INTERNATIONAL PKWY DR, STE 100
RICHARDSON TX 75081
972-437-6700

Certificate of Calibration

Date: Apr 15, 2015

Cert No. 222008122479748

Customer:

SMITH PUMP COMPANY INC
301 M & B INDUSTRIAL
WACO TX 76712

MPC Control #: CE0570
Asset ID: CE0570
Gage Type: LIQUID FLOWMETER
Manufacturer: GE PANAMETRICS
Model Number: PT878
Size: N/A
Temp/RH: 72°F / 44 %

Work Order #: TX-8005832
Purchase Order #: PU36823
Serial Number: 02368
Department: N/A
Performed By: AMY BOLAM
Received Condition: IN TOLERANCE
Returned Condition: IN TOLERANCE
Cal. Date: April 15, 2015
Cal. Interval: 12 MONTHS
Cal. Due Date: April 15, 2016

Calibration Notes:

Standards Used to Calibrate Equipment

I.D.	Description.	Model	Serial	Manufacturer	Cal. Due Date	Traceability #
CC6851	CALIBRATOR	5720A	6985201	FLUKE	Jul 1, 2015	222008122362473
CD6016	FUNCTION GENERATOR	3325A	2512A21513	HEWLETT PACKARD	Jan 18, 2016	222008122443493
CE9042	DECADE RESISTOR	DB62	1946002	ESI ELECTRONICS	Feb 6, 2016	222008122400368

Procedures Used in this Event

Procedure Name	Description
MPC-00089	Flow Meters Liquid and Gas

Calibrating Technician:

AMY BOLAM

QC Approval:

RICK HERNANDEZ

The reported expanded uncertainty of measurement is stated as the standard uncertainty of measurement multiplied by the coverage factor $k=2$, which for normal distribution corresponds to a coverage probability of approximately 95%. The standard uncertainty of measurement has been determined in accordance with EA's Publication and NIST Technical Note 1297, 1994 Edition. Services rendered comply with ISO 17025:2005, ANSI/NCCL Z540-1, MPC Quality Manual, MPC CSD and with customer purchase order instructions.

Calibration cycles and resulting due dates were submitted/approved by the customer. Any number of factors may cause an instrument to drift out of tolerance before the next scheduled calibration. Recalibration cycles should be based on frequency of use, environmental conditions and customer's established systematic accuracy. The information on this report, pertains only to the instrument identified.

All standards are traceable to SI through the National Institute of Standards and Technology (NIST) and/or recognized national or international standards laboratories. Services rendered include proper manufacturer's service instruction and are warranted for no less than thirty (30) days. This report may not be reproduced in part or in a whole without the prior written approval of the issuing MPC lab.

Equip. No. 163665



7575 Dillon Street
Houston, TX 77061-2826
Phone: (713)-641-2282
Fax: (713)-641-3371
Toll Free: (800)-914-0009
www.TEXASGAUGE.com

CALIBRATION

Part Number **ASHCROFT 30 PSI** Serial Number **TGC-7101**
Pressure Range **0-30 PSI** Accuracy **+/- .25** Full Scale
Customer **SMITH PUMP COMPANY, INC**
PO Number: **PU32376** Order ID: **73599**

CALIBRATION CERTIFICATE PRESSURE GAUGE

AS FOUND PRESSURE		INCREASING PRESSURE		DECREASING PRESSURE	
Increasing	Decreasing	Standard	Reading	Standard	Reading
0	29.98	0	0	30	29.98
7.62	15.02	7.6	7.62	15	15.02
15.02	7.6	15	15.02	7.6	7.6
30.02	0	30	30.02	0	0

Calibrated In **Vertical** Position

Temperature **72**

THIS IS TO CERTIFY THAT THIS GAUGE HAS BEEN INSPECTED AND TESTED AGAINST PRESSURE STANDARD #918933 (11/12/2014) TRACEABLE TO THE NATIONAL BUREAU OF STANDARDS, TRACEABILITY REFERENCE NIST Test #072-FP75-23 COMPENSATED TO LOCAL ACCELERATION DUE TO GRAVITY.

Special Conditions: **READINGS IN PSI**

Calibration Date: **6/10/2014**

Inspector: _____



7575 Dillon Street
Houston, TX 77061-2826
Phone: (713)-641-2282
Fax: (713)-641-3371
Toll Free: (800)-914-0009
www.TEXASGAUGE.com

CALIBRATION

Part Number ASHCROFT 30"HG Serial Number TGC-7101
Pressure Range 0-30"HG Accuracy +/- .25 Full Scale
Customer SMITH PUMP COMPANY, INC
PO Number: PU32376 Order ID: 73599

CALIBRATION CERTIFICATE PRESSURE GAUGE

AS FOUND PRESSURE		INCREASING PRESSURE		DECREASING PRESSURE	
Increasing	Decreasing	Standard	Reading	Standard	Reading
0	29	0	0	29	29
10	20	10	10	20	20
20	10	20	20	10	10
29	0	29	29	0	0

Calibrated In Vertical Position

Temperature 72

THIS IS TO CERTIFY THAT THIS GAUGE HAS BEEN INSPECTED AND TESTED AGAINST PRESSURE STANDARD #918933 (11/12/2014) TRACEABLE TO THE NATIONAL BUREAU OF STANDARDS, TRACEABILITY REFERENCE NIST Test #072-FP75-23 COMPENSATED TO LOCAL ACCELERATION DUE TO GRAVITY.

Special Conditions: READINGS IN "HG

Calibration Date: 6/10/2014

Inspector: 

Equip. No. 163665



7575 Dillon Street
Houston, TX 77061-2826
Phone: (713)-641-2282
Fax: (713)-641-3371
Toll Free: (800)-914-0009
www.TEXASGAUGE.com

CALIBRATION

Part Number ASHCROFT 460'FT H20 Serial Number 163665
Pressure Range 0-460'FT H20 Accuracy +/- .25 Full Scale
Customer SMITH PUMP COMPANY, INC
PO Number: PU32376 Order ID: 73599

**CALIBRATION CERTIFICATE
PRESSURE GAUGE**

AS FOUND PRESSURE		INCREASING PRESSURE		DECREASING PRESSURE	
Increasing	Decreasing	Standard	Reading	Standard	Reading
0	459.48	0	0	460	459.48
100.8	349.92	100	100.8	350	349.92
229.05	229.97	230	229.05	230	229.97
350.15	99.87	350	350.15	100	99.87
459.48	0	460	459.48	0	0

Calibrated In Vertical Position

Temperature 72

THIS IS TO CERTIFY THAT THIS GAUGE HAS BEEN INSPECTED AND TESTED AGAINST PRESSURE STANDARD #918933 (11/12/2014) TRACEABLE TO THE NATIONAL BUREAU OF STANDARDS, TRACEABILITY REFERENCE NIST Test #072-FP75-23 COMPENSATED TO LOCAL ACCELERATION DUE TO GRAVITY.

Special Conditions: **READINGS ARE IN FT H20**

CalibrationDate: 6/10/2014

Inspector: 

Certificate of Calibration

For Instrument: Extech 380976 Power Clampmeter
Serial Number: PM2000
Asset Number: 9147

CUSTOMER: Smith Pump Company
301 M&B Industrial
Waco TX 76712

The Meter Shop certifies that the above listed instrument meets or exceeds all specifications as stated in the referenced procedure (unless otherwise noted). It has been calibrated using measurement standards traceable to the National Institute of Standards and Technology (NIST), or to NIST accepted intrinsic standards of measurement, or derived by the ratio type of self-calibration techniques. This calibration complies with MIL-STD-45662A and ANSI/NCSL Z540-1-1994. and ISO 17025

This report may not be reproduced, except in full, unless permission for the publication of an approved abstract is obtained in writing from the calibration organization issuing this report.

CALIBRATION INFORMATION

Cal Date: 10 Oct 2014	Temperature 23.0°C	Pass Y
Next Cal Due: 10 Oct 2015	Humidity 43 %	Seals OK Y
Remarks: AS-FOUND : 120210916		
Cal Procedure Manufactures Specifications.	Revision	\$Revision: 1.4 \$

STANDARDS USED FOR CALIBRATION

Asset Number	Description	Cal. Date	Due Date
5001	Fluke 5520A Calibrator	30 Jul 2014	29 Jul 2015

Signed: 

SERIAL NUMBER: PM2000

ASSET NUMBER: 9147

PRINTED ON: 10 Oct 2014

Certificate of Calibration or Failed Calibration Report

Page 1 of 1

Equip. No. 168553

CERTIFICATE of INSPECTION

Product: VIBSCANNER/smartSCANNER Model# VIB 5.400

P.O. No.: PU36844

Customer: SMITH PUMP COMPANY, INC.

This is to certify that the subject Data Collector was inspected at:



LUDECA

LUDECA INC.

1425 N.W. 88th Avenue
Miami, FL 33172

Phone No.: (305) 591-8935

Fax No.: (305) 591-1537

This inspection was conducted in accordance with the Ludeca's inspection procedure# LUDC1014-00. Ludeca's Inspection Certificate is in compliance of ANSI/NCSL Z540-1-1994. The calibration station utilizes a Model VC11 vibration calibrator. Vibration measurements were recorded at 159 Hz at a nominal temperature of 20°C. This certificate may not be reproduced, except in full, without the written approval of Ludeca, Inc. This certificate package consists of 1 pages.

Date of Inspection: **April 22, 2015**

Valid Through: **April 22, 2017**

Instrument Serial No.: **03642**

HW - Status **3.01**

Inspector: **Regie Romo**

Initials rr

Results

	As Found	Deviation	As Left	Deviation	Allowable
Velocity Sensitivity (Ref 10.27 mm/s)	10.34	0.68%	10.32	0.48%	±5%
Temperature Deviation °F, Ref/Test:	136.76/139	1.63%	134.26/135	0.55%	±3%


Q.A. INSPECTOR


LUDECA, INC.

VC11 is traceable by comparison calibration with a NIST certified primary standard thru PCB certificate #cal3-3459235878.429. Reference: Output for 175.3 gram mass = $10.27\text{m/s}^2 = 10.27\text{mm/s @ } 159.2\text{ Hz}$.

VC11 Serial No.: 990999

Certificate Dated: 12-AUG-2014

Due: 12-AUG-2015

The Precision RTD Thermometer, Model 407907 is traceable to NIST ITS-90 through Certificate 110841/6606. Reference Temperature actual ($\geq 100^\circ\text{F}$).

Precision RTD & Meter Serial No.: Z026266

Certificate Dated: 20-MAY-2014

Due: 20-MAY-2015

Printed: 4/23/2015 12:11 PM

SRVC-1823-01

CERTIFICATE of INSPECTION

Product: ALIGNEO TRANSDUCER MODEL# ALI 11.100

P.O. No.: PU30440

Customer: SMITH PUMP COMPANY, INC.

This is to certify that the subject Transducer was inspected at:



LUDECA

LUDECA INC.

1425 N.W. 88th Avenue
Miami, FL 33172

Phone No.: (305) 591-8935

Fax No.: (305) 591-1537

This inspection was conducted in accordance with Ludeca's inspection procedure# LUDC1012-02 dated, October 5, 2011. Ludeca's Inspection Certificate is in compliance of ANSI/NCSL Z540-1-1994. The calibration station utilizes a Master Set of gage blocks traceable to the *National Institute of Standards and Technology*. Measurements were recorded using the metric conversion of 1 inch = 25.4mm. This certificate may not be reproduced, except in full, without the written approval of Ludeca, Inc. This certificate package consists of 2 pages.

Date of Inspection: February 11, 2014

Due: February 11, 2016

Transducer S/N: 1207 1272

ALI 5.110 Prism S/N: 1407 9959

Inspector: Damien Hamm

Initials: D.H.

Results

Total RMS error Laser Detector: 1.06%

Maximum allowable Error = 2%

Average Angular Deviation: 0.95°

Maximum allowable Deviation = 2°


Q. A. INSPECTOR


LUDECA, INC.

The Gage Block Set is a certified primary standard traceable to NIST through Certificate of Calibration #651429. The set is calibrated annually with a maximum uncertainty of 0.10 micrometers.

Gage Block Serial No.: SET 1

Certificate Dated: 15-NOV-2013

Expires: 15-NOV-2014

CaliChek-F® Serial No.: 4895855

Certificate Dated: 06-MAY-2013

Expires: 06-MAY-2015

CaliChek-T® Serial No.: 2898061



Certificate Dated: 24-APR-2013

Expires: 24-APR-2014

IN/OUT DATA SHEET

LUDECA, INC.	Item: ALI 11.100	
Customer: SMITH PUMP COMPANY, INC.	Serial Number: 1207 1272	
	Date Received: February 5, 2014	Date Completed: February 11, 2014
	Received via: UPS Shipped via: FEDEX	
Incoming Condition: Used		
Description of Fault: NIST calibration; no defects were found that affect accuracy or linearity. No adjustments were made and no parts were used.		

DEFECTIVE PARTS Name of parts/Subassembly	PART NUMBER	FAULT DESCRIPTION	WARRANTY

Repair:	As found and as shipped readings are identical.	
<p>COMMENTS: The procedure and NIST Traceable standards used provide a measurement uncertainty that is at least equal to or better than four (4) times the specification of the unit under test. The procedures were performed at 68.5°F nominal, 46.4% humidity and in conformance with P. O. Number PU30440</p>		
Date: February 11, 2014	 Q.A. INSPECTOR	Technician:  Damien Hamm